



# ACCIDENT/ INCIDENT INVESTIGATION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	EER, Inc.	<b>Project</b>	SONY
<b>Date of Incident</b>	December 16, 2024	<b>Time of Incident</b>	05:38 AM
<b>Date of Investigation</b>	December 16, 2024	<b>Time of Investigation</b>	06:38 AM
<b>Investigator</b>	joe morales	<b>Type of Incident</b>	Injury

## EMPLOYEE INFORMATION

**Employee Name**  
albert padilla

**Nature Of Injury**  
no injuries just the trailer

## DESCRIPTION OF INCIDENT

Albert was the driver

## WITNESSES & STATEMENTS

<b>Name</b>	<b>Company</b>	<b>Statement</b>
none	eer	None

## COMMENTS & PHOTOS

<b>comment</b>	<b>Image</b>
----------------	--------------

## ROOT CAUSE

Over loading the trailer

## CONTRIBUTING FACTORS

Too much debris plus a terminator

## INVESTIGATOR SIGNATURE

A handwritten signature in black ink, appearing to read "G. M. L.", is located in the upper left corner of the page.

## CORRECTIVE ACTION

Unloading some debris from the overloaded trailer

## ADDITIONAL INFORMATION

None