





PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	December 13, 2023
Inspector Name	Connor Gregory	Time of Inspection	02:42 PM

INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Unsatisfactory	Under generator. Missing 1-1/2" RMC	
Was work completed?	Satisfactory	Both sections of panel ML3 taken down and plywood backing moved over to accommodate 3" feeder pipe coming through floor underneath. Most of the hanging cables have been identified and found out in field for future termination.	
Was work completed?	Satisfactory	Investigated the roof top penetrations and how to route cables to each unit. Investigated the sub panel feeds and how to route conduit to each panel.	-
Was work completed?	N/A		-
Was work completed?	N/A		-

UNSATISFACTORY ITEMS

Photo	Comment	Corrective Action
-------	---------	-------------------