








PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	February 16, 2024
Inspector Name	Connor Gregory	Time of Inspection	03:00 PM

INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	Adam Justin and kris pulling sub panel feeders from first floor to second floor,	
Was work completed?	Satisfactory	Nick and Sal worked up and putting in the trims for high hats on mezzanine floor	
Was work completed?	Satisfactory	Jake still prepping and cutting in panels on second floor	

<p>Was work completed?</p>	<p>Satisfactory</p>	<p>Jared and Tomas pulling wire on mezzanine in training area for normal and emergency lights and controls</p>	 A photograph showing a dark, tiled mezzanine floor. A bundle of green and blue wires is being pulled across the floor. A yellow caution tape is visible along the edge of the floor.
<p>Was work completed?</p>	<p>Satisfactory</p>		 A photograph showing a staircase with a metal handrail. The wall behind the staircase is made of concrete blocks. Some tools are visible on the floor near the base of the stairs.