



# PROJECT INSPECTION


Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

|                       |                |                            |                    |
|-----------------------|----------------|----------------------------|--------------------|
| <b>Company</b>        | ABC & Co.      | <b>Type of Inspection:</b> | Roofing Inspection |
| <b>Project</b>        | Project 2 Test | <b>Date Of Incident</b>    | June 18, 2018      |
| <b>Inspector Name</b> | user@gmail.com | <b>Time Of Incident</b>    | 10:17 PM           |

## INSPECTION ITEMS

| Item   |                | Comment               |
|--|----------------|-----------------------|
| Fall Protection  | Satisfactory   |                       |
| Trenching & excavation work being done safely            | Satisfactory   |                       |
| Trenching & excavation work being done safely            | Satisfactory   |                       |
| Scissor lifts / elevated platforms are being used safely | Satisfactory   |                       |
| Tools & equipment are being used safely                  | Unsatisfactory | This is not very good |
| Personal Protective Equipment is being worn as required  | Satisfactory   |                       |
| Are Safety Nets set up safely                            | Satisfactory   |                       |

## UNSATISFACTORY ITEMS

| Photo  | Comment         | Corrective Action |
|--|-----------------|-------------------|
|  | Trying this out |                   |