



# PROJECT INSPECTION


Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	ABC & Co.	<b>Type of Inspection:</b>	Trenching & Excavation Inspection
<b>Project</b>	Project 3 Test	<b>Date Of Incident</b>	June 17, 2018
<b>Inspector Name</b>	user@gmail.com	<b>Time Of Incident</b>	01:20 AM

## INSPECTION ITEMS

Item		Comment
OSHA permit is present	Satisfactory	Nuuhuunuuhj
Is a protective system in place for the trench if 5' or deeper?	Satisfactory	
Are spoils at least 2' back from the top of the trench?	Unsatisfactory	

## UNSATISFACTORY ITEMS

Photo	Comment	Corrective Action
	Jjjijomom	
-	Okmiomomo	