



Builder Link® Trade Performance by Project For The Past 90 Days

Performance Rating Scale: 1 - 3 Unacceptable, 4 - 7 Acceptable, 8 - 10 Excellent

Project: Arbor Gates

| Trade Performance | Company Name | Trade Assignment |
|-------------------|----------------|------------------------|
| 10.0 | Superintendent | Concrete Footings |
| 10.0 | Superintendent | Concrete Forming |
| 10.0 | Superintendent | Concrete Reinforcement |
| 10.0 | Superintendent | Concrete Waterproofing |
| 10.0 | Superintendent | Plumbing |
| 10.0 | Superintendent | Roofing |

Project: Bella Vista II

| Trade Performance | Company Name | Trade Assignment |
|-------------------|----------------|---------------------------|
| 10.0 | Superintendent | Door Installation |
| 8.7 | Superintendent | Electrical |
| 10.0 | Superintendent | Exterior Cladding |
| 10.0 | Superintendent | Fire Sprinkler |
| 10.0 | Superintendent | Framing |
| 8.9 | Superintendent | HVAC |
| 10.0 | Superintendent | Lath Vendor |
| 10.0 | Superintendent | Lathing/Plastering |
| 9.0 | Superintendent | Plumbing |
| 10.0 | Superintendent | Roofing |
| 10.0 | Superintendent | Weather Resistive Barrier |
| 7.8 | Superintendent | Window Installation |

Project: Bonterra II

| Trade Performance | Company Name | Trade Assignment |
|-------------------|----------------|-------------------|
| 10.0 | Superintendent | Concrete Forming |
| 10.0 | Superintendent | Door Installation |
| 10.0 | Superintendent | Electrical |

Quality Built® The Next Generation of Quality Assurance®

633 S. Andrews Ave. Suite 204, Fort Lauderdale, FL 33301 800.547.5125

Email: customerservice@qualitybuilt.com

| | | |
|------|----------------|---------------------------|
| 10.0 | Superintendent | Exterior Cladding |
| 10.0 | Superintendent | Fire Sprinkler |
| 10.0 | Superintendent | Framing |
| 9.3 | Superintendent | HVAC |
| 10.0 | Superintendent | Lath Vendor |
| 10.0 | Superintendent | Lathing/Plastering |
| 8.2 | Superintendent | Plumbing |
| 10.0 | Superintendent | Roofing |
| 10.0 | Superintendent | Weather Resistive Barrier |
| 9.3 | Superintendent | Window Installation |
| 9.5 | Superintendent | Wood Framing |

Project: Hidden Oaks

| Trade Performance | Company Name | Trade Assignment |
|-------------------|----------------|---------------------------|
| 10.0 | Superintendent | Electrical |
| 10.0 | Superintendent | Exterior Cladding |
| 10.0 | Superintendent | Fire Sprinkler |
| 8.9 | Superintendent | HVAC |
| 10.0 | Superintendent | Lath Vendor |
| 10.0 | Superintendent | Lathing/Plastering |
| 9.0 | Superintendent | Plumbing |
| 9.1 | Superintendent | Roofing |
| 10.0 | Superintendent | Weather Resistive Barrier |
| 10.0 | Superintendent | Wood Framing |

Project: Kensington II

| Trade Performance | Company Name | Trade Assignment |
|-------------------|----------------|------------------------|
| 10.0 | Superintendent | Concrete Footings |
| 10.0 | Superintendent | Concrete Forming |
| 10.0 | Superintendent | Concrete Reinforcement |
| 10.0 | Superintendent | Concrete Waterproofing |
| 10.0 | Superintendent | Door Installation |
| 9.4 | Superintendent | Electrical |
| 10.0 | Superintendent | Exterior Cladding |
| 10.0 | Superintendent | Fire Sprinkler |
| 10.0 | Superintendent | Framing |

Quality Built® The Next Generation of Quality Assurance®

633 S. Andrews Ave. Suite 204, Fort Lauderdale, FL 33301 800.547.5125

Email: customerservice@qualitybuilt.com

| | | |
|------|----------------|---------------------------|
| 9.6 | Superintendent | HVAC |
| 10.0 | Superintendent | Lath Vendor |
| 9.1 | Superintendent | Lathing/Plastering |
| 7.9 | Superintendent | Plumbing |
| 10.0 | Superintendent | Roofing |
| 10.0 | Superintendent | Superintendent |
| 8.0 | Superintendent | Weather Resistive Barrier |
| 9.3 | Superintendent | Window Installation |
| 9.5 | Superintendent | Wood Framing |

Project: Quail Run Ph II

| Trade Performance | Company Name | Trade Assignment |
|-------------------|----------------|------------------------|
| 10.0 | Superintendent | Concrete Footings |
| 10.0 | Superintendent | Concrete Forming |
| 10.0 | Superintendent | Concrete Reinforcement |
| 10.0 | Superintendent | Concrete Waterproofing |
| 10.0 | Superintendent | Electrical |
| 10.0 | Superintendent | Plumbing |

Project: San Rio

| Trade Performance | Company Name | Trade Assignment |
|-------------------|----------------|---------------------------|
| 10.0 | Superintendent | Electrical |
| 10.0 | Superintendent | Exterior Cladding |
| 10.0 | Superintendent | Fire Sprinkler |
| 6.3 | Superintendent | Framing |
| 10.0 | Superintendent | HVAC |
| 10.0 | Superintendent | Lath Vendor |
| 10.0 | Superintendent | Lathing/Plastering |
| 10.0 | Superintendent | Plumbing |
| 10.0 | Superintendent | Weather Resistive Barrier |
| 10.0 | Superintendent | Window Installation |

Project: San Rio Ph2 - Site Safety has no data at this time

| Trade Performance | Company Name | Trade Assignment |
|-------------------|--------------|------------------|
|-------------------|--------------|------------------|

Quality Built® The Next Generation of Quality Assurance®

633 S. Andrews Ave. Suite 204, Fort Lauderdale, FL 33301 800.547.5125

Email: customerservice@qualitybuilt.com

Project: San Rio Ph2(Frankwood Commons)

| Trade Performance | Company Name | Trade Assignment |
|-------------------|----------------|------------------------|
| 10.0 | Superintendent | Concrete Footings |
| 10.0 | Superintendent | Concrete Forming |
| 10.0 | Superintendent | Concrete Reinforcement |
| 10.0 | Superintendent | Concrete Waterproofing |
| 10.0 | Superintendent | Electrical |
| 10.0 | Superintendent | Plumbing |

Project: Sterling Oaks

| Trade Performance | Company Name | Trade Assignment |
|-------------------|----------------|------------------------|
| 10.0 | Superintendent | Concrete Footings |
| 10.0 | Superintendent | Concrete Forming |
| 10.0 | Superintendent | Concrete Reinforcement |
| 10.0 | Superintendent | Concrete Waterproofing |
| 10.0 | Superintendent | Electrical |
| 10.0 | Superintendent | Plumbing |

Project: Summerlin Phase 3 (Andersen Village)

| Trade Performance | Company Name | Trade Assignment |
|-------------------|----------------|---------------------------|
| 10.0 | Superintendent | Concrete Footings |
| 10.0 | Superintendent | Concrete Forming |
| 10.0 | Superintendent | Concrete Reinforcement |
| 10.0 | Superintendent | Electrical |
| 10.0 | Superintendent | Exterior Cladding |
| 10.0 | Superintendent | Fire Sprinkler |
| 10.0 | Superintendent | HVAC |
| 1.0 | Superintendent | Lath Vendor |
| 10.0 | Superintendent | Lathing/Plastering |
| 9.3 | Superintendent | Plumbing |
| 10.0 | Superintendent | Weather Resistive Barrier |
| 10.0 | Superintendent | Wood Framing |

Quality Built® The Next Generation of Quality Assurance®

633 S. Andrews Ave. Suite 204, Fort Lauderdale, FL 33301 800.547.5125

Email: customerservice@qualitybuilt.com

© 2022 Quality Built, LLC. All Rights Reserved.

Report Time: 7/3/2022 7:51:23 AM

Page 4 of 5

This report contains confidential and proprietary information of Quality Built and is protected by copyright, trade secret and other State and Federal laws. Its receipt or possession does not convey any rights to reproduce, disclose, or manufacture, use or sell anything it may contain or describe. Reproduction, disclosure, or use without specific written authorization of Quality Built is strictly prohibited.

Project: Tiffany Ranch

| Trade Performance | Company Name | Trade Assignment |
|--------------------------|---------------------|---------------------------|
| 10.0 | Superintendent | Door Installation |
| 10.0 | Superintendent | Electrical |
| 10.0 | Superintendent | Exterior Cladding |
| 10.0 | Superintendent | Fire Sprinkler |
| 10.0 | Superintendent | Framing |
| 10.0 | Superintendent | HVAC |
| 10.0 | Superintendent | Lath Vendor |
| 7.8 | Superintendent | Lathing/Plastering |
| 10.0 | Superintendent | Plumbing |
| 10.0 | Superintendent | Roofing |
| 8.9 | Superintendent | Weather Resistive Barrier |
| 10.0 | Superintendent | Window Installation |
| 10.0 | Superintendent | Wood Framing |