SAFETY INSPECTION REPORT

CONDUCTED FOR: Chesmar Homes Austin

> **PROJECT:** Water Oak



INSPECTION TYPE: General Construction

INSPECTOR : DAN MOWERY DATE : JULY 29, 2024 CITY : GEORGETOWN STATE : TEXAS

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION			
53	18	5	30
Items Inspected	Satisfactory	Unsatisfactory	N/A

Met with the superintendent and then walked the job site. Scaffolding had a lot of issues, will be noted in pictures. Fall protection wasn't being worn. Ladders are being used. And there were some openings on the second floor that need a rail going across the open, for fall protection. No safety glasses were being used.

Housekeeping looked really good. There is a picture of a worker cleaning the street. Great job.

I did notice J & D sheet metal and roofing truck was on site. That was the only vehicle with any marking on it.

INSPECTION ITEMS

Documentation	
Site Contact	Satisfactory
Safety Program (Including IIPP)	Satisfactory
Heat Illness Prevention Program	N/A
Safety Data Sheets	Satisfactory
Daily Inspections	N/A
Tailgate Meetings	N/A
Sub-Contractor Meetings	N/A
OSHA Permits	Satisfactory
Labor Law Postings	Satisfactory

Emergency / Other Postings	Satisfactory
First Aid / CPR Certification	Satisfactory
Emergency Items	
Access / Egress	N/A
Elevator for Hoisting Workers (if needed)	N/A
Fire Extinguisher(s)	Satisfactory
First Aid Kit(s)	Satisfactory
Eye Wash Station	Satisfactory
Other Fire Fighting Equipment (If needed)	N/A
General Items	
Restrooms	Satisfactory
Hand Washing Stations	Satisfactory
Waste Containers	Satisfactory
Potable Water	N/A
Shade	N/A
Shade Tools & Equipment	N/A
	N/A Satisfactory

I'll power tools were being used in a safely manner.

-

Satisfactory

Hand Tools	Satisfactory
Powder Actuated Tools	N/A

Powder Actuated Tools

Pneumatic Nailers

Comment

Nailer was working fine



Mobile Elevated Work Plarforms (MEWP's)	N/A
Powered Industrial Trucks	N/A
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	N/A

Ladders	Unsatisfactory	
Comment		
Ladder is being used improperly		

Operations

Personal Protective Equipment

Comment

Most all of the workers were wearing hardhats, there was a couple incidents where they weren't wearing safety glasses.

Trenching & Excavation

Fail Protection Unsatisfactory Comment No fall protection was being worn, there was a roofer without fall protection. And a framer on a pump scaffolding wasn't wearing any fall protection. Image: Colspan="2">Image: Colspan="2" Image: Colspan="2" Image:

Guardrails

N/A

Unsatisfactory

Floor / Wall Openings

Satisfactory



N/A

N/A

Comment

Opening on second floor needs to have a rail going across it, for fall protection



Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	Unsatisfactory

Comment	
Scaffolding was missing a lot of parts, mud seals, base plates. Noted in pictures.	
No base plate	
Confined Spaces	N/A

N/A

Unsatisfactory

N/A

N/A

N/A

Roofing Operations

Comment

No fall protection, being worn by this roofer



Housekeeping	Satisfactory
Comment	
Housekeeping was really good	
Demolition	N/A
Silica Control	N/A
Rigging Operations	N/A

Hot Work

Electrical Safety

Lockout / Tagout

Stairways, Ramps, Runways	N/A
Other Items (that were observed)	N/A