# **SAFETY INSPECTION REPORT**

**CONDUCTED FOR:** Greystone Plastering

## **PROJECT:**

19673 Juniper Loop



## **INSPECTION TYPE:** Scaffolding Site Review

INSPECTOR: JOSHUA JOHNSON DATE: FEBRUARY 26, 2025 CITY: MORGAN HILL STATE: CA SITE CONTACT: N/A ADDITIONAL SITE CONTACT: N/A

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

Satisfactory

Satisfactory

Satisfactory

# SUMMARY OF INSPECTION42<br/>Items Inspected35<br/>Satisfactory3<br/>Unsatisfactory4<br/>N/A

A site inspection was carried out on-site today and I was able to walk the site and look for any safety concerns. Scaffolding is still up around many of the buildings.

Note the following good items that were observed:

- + No electrical concerns observed.
- + Materials are staged neatly.
- + Green tags are in place in some locations.

Note the following violations that need to be addressed:

#### Ladders:

- A extension ladder used for access was setup on a scaffold. This is not allowed. Note: Extension ladders used for access must extend 3 feet past the level being accessed, have a 4:1 ratio and be secured. Extension ladders are not allowed to be setup on a scaffold.

- Toe boards are missing from access/egress areas. Ensure they are added.

- Ensure hatches are closed when not in use. A open hatch is a fall hazard.

Overall, the site was found in satisfactory condition.

ooo Please see additional report notations below. ooo

# **INSPECTION ITEMS**

### Documentation

Safety Manual

#### **Tailgate Meetings**

#### SDS

Inspection Tags / Daily Inspection	Satisfactory
Comment	-
In place in some locations. A few appeared to be missing.	
Labor Law Posters	Satisfactory
Codes/Emergency Posters	Satisfactory
Written Heat Illness Prevention Program	Satisfactory
OSHA Permits	Satisfactory
First Aid/CPR Cert	Satisfactory
Restrooms/Wash Stations	Satisfactory
Comment	
Restrooms are available in stocked.	-
Waste Containers	Satisfactory
Emergency Items	
Fire Extinguisher	Satisfactory
Comment	
Fire extinguishers are available on site.	-
First Aid Kit	Satisfactory

Greystone Plastering   19673 Juniper Loop	Feb 26, 2025
Comment	
First aid kits are available on site.	-
Water Supply	Satisfactory
Shade	Satisfactory
Comment	
Provided by the building and scaffold.	-
General Items	
Silica Exposure Control	N/A
Personal Protective Equipment	Satisfactory
Comment	
No concerns observed.	-
Power Tools	Satisfactory
Hand Tools	Satisfactory
Power Saws	N/A
Electrical Safety	Satisfactory
Comment	-
Ensure scaffolding, workers, tools, and materials stay a safe distance away from electrical lines in the area of the scaffold.	

## Ladder Safety

# Comment Use of a ladder on a scaffold is not allowed. Ensure the ladder is removed and workers received training so that they understand ladder and scaffold safety better. Stairway/Ramps/Runways Satisfactory **Material Storage Satisfactory Impalement Hazards** Satisfactory **Traffic Control** Satisfactory **Powered Industrial Trucks** N/A Housekeeping Satisfactory Comment Overall good. Some areas need improved housekeeping. \_ Scaffolding Secure Surface / Mud Sills and Nailed Satisfactory

Comment

Most mud sills have at least two nails. A few are missing nails.



Base Plates/Jacks	Satisfactory
Level and Plumb	Satisfactory
Comment	
No concerns observed.	-
Cross/Horizontal Braces	Satisfactory
Comment	•
Most are in good shape, but a few are showing signs of damage. Ensure that damaged cross braces are replaced.	-
Planks	Satisfactory
Guardrails/End Rails	Satisfactory
Toe Boards	Unsatisfactory
Comment	-

In many locations, the garage is being used for access/egress. Ensure toe boards are installed above these locations.



Weight Capacity

Satisfactory

Anchor/Tipping Points	Satisfactory
Comment	-
Continue to ensure that all necessary anchors are in place.	-
Distance to Adjacent Wall	Satisfactory

#### Access/Egress

Unsatisfactory

Comment

-

Ensure hatches are kept closed.	
Uplift Pins In Place	Satisfactory
Distance from Power Lines	Satisfactory
Comment	-
See electrical safety comment above.	-
Suspended Scaffolding	N/A