SAFETY INSPECTION REPORT

CONDUCTED FOR:

Krikorian Construction, Inc.

PROJECT: 873 3rd St



INSPECTION TYPE:General Construction

INSPECTOR: LINDSEY CRAVEN

DATE: APRIL 29, 2024 CITY: MANHATTAN BEACH

STATE: CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION			
52	23	7	22
Items Inspected	Satisfactory	Unsatisfactory	N/A

Contractors on site:

ALP Painting
Crane Plumbing
GMac Electrical

Painting contractors were sanding throughout house. They were wearing N95 masks and working safely on ladders.

Electrician was making a materials list.

Crane plumbing was walking the site with Dan and crew was working in the bathrooms.

INSPECTION ITEMS Documentation **Site Contact Satisfactory** Comment Adam was on site. Safety Program (Including IIPP) Satisfactory **Heat Illness Prevention Program** Satisfactory **Safety Data Sheets** Satisfactory **Daily Inspections** Satisfactory **Tailgate Meetings** Satisfactory

Sub-Contractor Meetings

Satisfactory

OSHA Permits

N/A

Labor Law Postings

Unsatisfactory

Comment

Updated 2024 postings needed from office.

Emergency / Other Postings

Satisfactory

Comment

Route to nearest medical facility is posted.



First Aid / CPR Certification

Satisfactory

Emergency Items

Access / Egress

Satisfactory

Fire Extinguisher(s)

Satisfactory

First Aid Kit(s)

Satisfactory

Comment

Located in garage.



Eye Wash Station	Satisfactory
Comment	
Located in first aid kit.	-

Other Fire Fighting Equipment (If needed)

N/A

General Items	
Restrooms	Satisfactory
Comment	
Available on site.	-

Hand Washing Stations

Unsatisfactory

Comment

Handwashing station is fully stocked, but it cannot be accessed because of where materials are being stored.



Waste Contatiners	Unsatisfactory
Comment	
No waste containers available near the wash station.	-

Potable Water Satisfactory

Shade	Satisfactory
Comment	
Building being used as means of shade	-

Tools & Equipment

Cranes N/A

Hand Tools	Satisfactory
Comment	
No hazards observed.	-
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Powder Actuated Tools	N/A
Cylinder Storage	N/A
Pneumatic Nailers	N/A
Ladders	Unsatisfactory
Comment	
Many ladders on site are missing the required safety stickers. Some are covered in paint or other material. Ensure replacement safety stickers are purchased and ladders are in good repair.	
Top cap of ladder is damaged. Ladder should be removed from site.	
Mobile Elevated Work Plarforms (MEWP's)	N/A
Powered Industrial Trucks	N/A
Power Tools	Satisfactory

Operations

Trenching & Excavation

Unsatisfactory

Comment

Until the pool is filled, delineation with caution tape is needed around pool area.



Electrical Safety Unsatisfactory

Comment

String lights need to be mounted up off the ground and sockets are needed as these are live energized exposed parts.



Housekeeping	Satisfactory
Comment	
Site is clean. Trash is being kept in one place at front of site.	-
Suspended Scaffolding	N/A
Fall Protection	N/A
Lockout / Tagout	N/A
Demolition	N/A

Confined Spaces	N/A
Guardrails	Satisfactory
Comment	
Permanent guardrails are in place on stairways.	-
Stairways, Ramps, Runways	Satisfactory
Silica Control	N/A
Impalement Hazards	N/A
Other Items (that were observed)	N/A
Floor / Wall Openings	Satisfactory
Rigging Operations	N/A
Traffic Control	N/A
Supported Sacffolding	Unsatisfactory
Comment	
Scaffolding inside the building has bases that are not secured to mud sills. Frame must be double nailed to mud sill.	

End rails and interior guard rails are missing.



Guard rails are missing at top level of scaffolding at front of house.



Midrail is missing and adjoining midrail is unattached to frame.



Toe board is in place on upper level in this photo where stone is present on the scaffolding. Toe board is needed on lower level also.



Plank is missing. All frames must be fully planked.



All scaffolding on site must be red-tagged as "Do Not Use" and no one should be allowed to use it until it is made safe by a qualified erector and a competent person signs off on it.

A green tag/red tag system is recommended where the competent person inspects the scaffold daily and signs off when it is safe to use.

-

Personal Protective Equipment	Satisfactory
Comment	
Painters were wearing N95 masks while sanding.	-

Hot Work	N/A
Roofing Operations	N/A
Mobile Scaffolding	N/A