SAFETY INSPECTION REPORT

CONDUCTED FOR:

Lennar Homes of California, LLC

PROJECT:

Greenwood - Tracy Hills



INSPECTION TYPE:General Construction

INSPECTOR: JORDAN DUZI

DATE: MAY 23, 2024

CITY: TRACY STATE: CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION 52 Items Inspected 5 Unsatisfactory 15 N/A

Site was in good overall condition.

Concrete pour was taking place.

Good overall PPE

Low windows have railing

Scaffold being set.

Access ladders to roof were blocked at the bottom - ensure they're secured on top. Correctly extending 3 ft.

Toe boards are up.

Counter top workers had respirators.

Lot 70 scaffold missing some railing on lower roof area.

Roofer had harness on but wasn't tied off.

Anchor bolts/all threads need to be capped on foundations.

INSPECTION ITEMS

Documentation	
Site Contact	Satisfactory
Comment	
Jim Lamb	-

Safety Program (Including IIPP)	Satisfactory
Comment	

	1
Safety Program is available	-
Heat Illness Prevention Program	Satisfactory
Safety Data Sheets	Satisfactory
Daily Inspections	Satisfactory
Comment	
Daily inspections are being performed	-
Tailgate Meetings	Satisfactory
Comment	
Tailgates are being conducted at least every 10 working days	-
Sub-Contractor Meetings	N/A
OSHA Permits	Satisfactory
Labor Law Postings	Satisfactory
Comment	
Labor law postings are in place as required.	-
Emergency / Other Postings	Satisfactory
First Aid / CPR Certification	
Thist Aid / GFR Gertinication	Satisfactory
Emergency Items	Satisfactory
	Satisfactory Satisfactory
Emergency Items	
Emergency Items Access / Egress	Satisfactory

Other Fire Fighting Equipment (If needed)	N/A
General Items	
Restrooms	Satisfactory
Hand Washing Stations	Satisfactory
Waste Contatiners	Satisfactory
Potable Water	Satisfactory
Shade	Satisfactory
Tools & Equipment	
Power Tools	Satisfactory
Comment Grinder had guard installed	<u>-</u>
Officer had guard installed	
Hand Tools	Satisfactory
Powder Actuated Tools	N/A
Pneumatic Nailers	Satisfactory
Mobile Elevated Work Plarforms (MEWP's)	N/A
Powered Industrial Trucks	Satisfactory
Heavy Mobile Equipment (Excavators, Loaders, etc)	Satisfactory
Cranes	N/A
Cylinder Storage	N/A

Ladders	Unsatisfactory
Comment	
Access ladders blocked at bottom but ensure they're tied off at top	-
Operations	
Personal Protective Equipment	Satisfactory
Comment	
PPE being worn throughout site	-
Trenching & Excavation	N/A
Fall Protection	Unsatisfactory
Comment	
Roofer not tied off	-
Guardrails	Satisfactory
Floor / Wall Openings	Satisfactory
Supported Scaffolding	Unsatisfactory
Comment	
Lot 70 scaffold missing rails on lower roof area.	-
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Unsatisfactory
Comment Anchor holto/all throads need to be conned	
Anchor bolts/all threads need to be capped	
Traffic Control	N/A

Roofing Operations	Unsatisfactory
Comment	
Roofer was wearing harness but wasn't tied off	-
łousekeeping	Satisfactory
Comment	
Could use attention around Lot 121 with excess foam	-
Demolition	N/A
Silica Control	Satisfactory
Comment	
Norker was alone with respirator on. If other workers are in the area, additional engineering controls will be needed.	-
Rigging Operations	N/A
lot Work	Satisfactory
Electrical Safety	Satisfactory
Comment	
Cords in good condition	-
Lockout / Tagout	N/A
Stairways, Ramps, Runways	Satisfactory
Other Items (that were observed)	Satisfactory