SAFETY INSPECTION REPORT

CONDUCTED FOR:

Lennar Homes of California, LLC

PROJECT:

Magnolia



INSPECTION TYPE:

General Construction

INSPECTOR: JORDAN DUZI DATE: FEBRUARY 28, 2025

CITY: PATTERSON

STATE: CA

SITE CONTACT: JUAN CARRILLO ADDITIONAL SITE CONTACT: N/A

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION			
52 Items Inspected	36 Satisfactory	1 Unsatisfactory	15 N/A

Site is in good overall condition

Workers installing exterior brick have dust control saw in place

Live outlet in use without cover plates - lot 208

Worker observed without harnesses on and not tied off - Lot 3B taping down plastic covering. CenCal. Foreman called and corrected by Lennar supervisor.

Lot 3B scaffold missing top rail

Roofers are within their trigger height and have access ladder secured

Shallow trench holes being worked in - delineation to go back up once work is complete

Framers have railing installed throughout windows. Forms being installed for upcoming pours.

Cords and tools in good condition throughout site.

OSHA Log 300A posted. 2025 Labor Law posters being delivered.

INSPECTION ITEMS

Documentation	
Safety Program (Including IIPP)	Satisfactory
Comment	
Safety Program is available	-

Heat Illness Prevention Program	Satisfactory

Safety Data Sheets Satisfactory

Daily Inspections		Satisfactory
Comment		
Daily inspections are being performed	-	
Tailgate Meetings		Satisfactory
Comment		
Failgates are being conducted at least every 10 working days	-	
Sub-Contractor Meetings		N/A
OSHA Permits		Satisfactory
Labor Law Postings		Satisfactory
Comment	Lennar	
2025 Labor Law posters being delivered to site	-	
Emergency / Other Postings		Satisfactory
Comment	Lennar	
DSHA Log 300A and all other emergency postings are up	-	
First Aid / CPR Certification		Satisfactory
Emergency Items		
Access / Egress		Satisfactory
Comment		
Access is compliant	-	
Elevator for Hoisting Workers (if needed)		N/A
Eiro Extinguichor(s)		Satisfactory
Fire Extinguisher(s)		

Eye Wash Station	N/A
Other Fire Fighting Equipment (If needed)	N/A
General Items	
Restrooms	Satisfactory
Comment	
In good condition	-
Hand Washing Stations	Satisfactory
Waste Containers	Satisfactory
Potable Water	Satisfactory
Shade	Satisfactory
Tools & Equipment	
Power Tools	Satisfactory
Comment	
Power tools in good condition	-
Hand Tools	Satisfactory
Powder Actuated Tools	Satisfactory
Pneumatic Nailers	Satisfactory
Mobile Elevated Work Plarforms (MEWP's)	N/A
Powered Industrial Trucks	Satisfactory
Comment	
No Ind trucks in use during walk	-

Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	N/A
Ladders	Satisfactory
Comment	
Good ladder safety observed throughout site	-
Comment	Roofer
Access ladder is secured	-
Operations	
Personal Protective Equipment	Satisfactory
Comment	
PPE being worn throughout site	-
Trenching & Excavation	Satisfactory
Comment	
Shallow trench holes being dug - delineation to go up	-
Fall Protection	Unsatisfactory
Comment	CenCal
Worker on exposed roof edge not tied off. Foreman called and worker corrected	-
Guardrails	Satisfactory
Comment	
nstalled timely	-
Floor / Wall Openings	Satisfactory
Comment	
No issues observed	

Supported Scaffolding	Satisfactory
Comment	CenCal
Scaffold in good overall condition - one off Lot 3B missing top rail	-
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Comment	
No impalement hazards observed	-
Traffic Control	N/A
Roofing Operations	Satisfactory
Comment	Roofer
Within trigger height	-
Housekeeping	Satisfactory
Comment	
Housekeeping in good overall condition	-
Demolition	N/A
Silica Control	Satisfactory
Comment	Masons
Exterior brick installers were using a dust control saw	-
Rigging Operations	N/A
Hot Work	Satisfactory

Electrical Safety	Satisfactory
Comment	
Cords in good condition. One off cover plate missing from live outlet - Lot 208	-
Lockout / Tagout	N/A
Stairways, Ramps, Runways	Satisfactory
Other Items (that were observed)	Satisfactory