## SAFETY INSPECTION REPORT

#### **CONDUCTED FOR:**

Lennar Homes of California, LLC

#### **PROJECT:**

Rangewood



### **INSPECTION TYPE:**

**General Construction** 

INSPECTOR: JORDAN DUZI DATE: NOVEMBER 18, 2024

CITY: TRACY STATE: CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION			
53 Items Inspected	<b>33</b> Satisfactory	<b>2</b> Unsatisfactory	<b>18</b> N/A

Site is busy and in good overall condition

Landscapers and all other trades doing a good job with PPE

Toe boards continue to be installed on scaffold with end rails in place. Lot 76 where plasterers were working was missing end rails on upper level

Temp guardrails are up in stairwells

Reminder to ensure vacuum attachment in place when hardie boards are being cut

General reminder to all trades that ladders should have legible decals and safety stickers - multiple ladders seen that were covered with paint or plaster.

Worker lot 1 installing gutters was not tied off and didn't have access ladder secured. Fall protection violation

Ensure CBC has end rails in place on active stacker bracket scaffold and is tied off on second floor roof where scaffold isn't present

# **INSPECTION ITEMS**

Documentation	
Site Contact	Satisfactory
Comment	
Phillip Booke	-
Safety Program (Including IIPP)	Satisfactory
Comment	
Safety Program is available	-
Hard III. and Bornes Carl Branco	Oatlafaataa
Heat Illness Prevention Program	Satisfactory

Comment	
Heat Illness Prevention Program is available and site specific information is completed.	-
Safety Data Sheets	Satisfactory
Daily Inspections	Satisfactory
Comment	
Daily inspections are being performed	-
Tailgate Meetings	Satisfactory
Comment	
Tailgates are being conducted at least every 10 working days	-
Sub-Contractor Meetings	N/A
OSHA Permits	N/A
Labor Law Postings	Satisfactory
Comment	
Labor law postings are in place as required.	-
Emergency / Other Postings	Satisfactory
Comment	
Emergency posters are on site and directions to nearest medical facility are posted.	-
First Aid / CPR Certification	Satisfactory
Emergency Items	
Access / Egress	Satisfactory
Elevator for Hoisting Workers (if needed)	N/A
,	

First Aid Kit(s)	Satisfactory
Eye Wash Station	N/A
Other Fire Fighting Equipment (If needed)	N/A
General Items	
Restrooms	Satisfactory
Comment	
Restrooms are on site and in good condition	-
Hand Washing Stations	Satisfactory
Comment	
On site	-
Waste Containers	Satisfactory
Potable Water	Satisfactory
Shade	Satisfactory
Comment	
Permanent structure provides shade	-
Ensure shade tents go up for workers installing forms when temp hits 80	-
Tools & Equipment	
Power Tools	Satisfactory
Comment	
In good condition	-
Hand Tools	Satisfactory
Powder Actuated Tools	Satisfactory

Pneumatic Nailers	Satisfactory
Comment	
Being operated safely	-
Mobile Elevated Work Plarforms (MEWP's)	N/A
Powered Industrial Trucks	Satisfactory
Comment	
Parked and not in use	-
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	N/A
Ladders	Unsatisfactor
Comment	
No violations but see note in summary about ensuring ladder decals are legible	-
Access ladder to roof - lot 1 - not secured	-
Operations	
Personal Protective Equipment	Satisfactory
Comment	
PPE being worn	-
Trenching & Excavation	N/A
Fall Protection	Unsatisfactor
Comment	

Also ensure CBC has railing installed on stacker bracket scaffold or
workers will need to be harnessed in and tied off at exposed areas. One
worker seen at leading edge where railing was down.

worker seem at leading edge where railing was down.	
Guardrails	Satisfactory
Comment	
Guardrails being installed timely in stairwells and landings	-
Floor / Wall Openings	Satisfactory
Comment	
No openings observed	-
Supported Scaffolding	Satisfactory
Comment	
Scaffold in good overall condition	-
One off area on Lot 76 where end rails were missing	-
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Comment	
No impalement hazards observed	-
Traffic Control	N/A
Roofing Operations	Satisfactory
Comment	
See note about gutter installer	-
Housekeeping	Satisfactory
_	

Comment

In good condition	-
Demolition	N/A
Silica Control	Satisfactory
Comment	
Siding not being cut during walk - reminder to ensure vacuum attachments are in place	-
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Satisfactory
Comment	
Cords in good condition	-
Lockout / Tagout	N/A
Stairways, Ramps, Runways	Satisfactory
Other Items (that were observed)	Satisfactory