# SAFETY INSPECTION REPORT

#### **CONDUCTED FOR:**

McCaffrey Homes

#### **PROJECT:**

tesoro Viejo



#### **INSPECTION TYPE:**

**General Construction** 

INSPECTOR: ESPITIA GUS DATE: AUGUST 21, 2024

CITY: MADERA STATE: CA.

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION			
53	29	4	<b>20</b>
Items Inspected	Satisfactory	Unsatisfactory	N/A

I met with Joe in the construction trailer, where he confirmed that he is conducting the daily inspections and weekly tailgate meetings. The safety program and permit binders are available in the trailer, and the federal and state posters are properly displayed. A fire extinguisher and first aid kit are also on-site.

As I walked the job site, I observed a Tri-Valley worker on lot 57 who was not wearing a hard hat and refused to comply when asked to do so. On lot 55, a JVC worker was cutting rock without wearing a dust mask or hard hat, which was corrected on site. Additionally, I noticed that the same worker had power drill, and the power cord was cut and added a section of an extension cord (see picture). Overall, the site maintained good housekeeping, and the restrooms were clean.

I had an exit meeting with Joe and reviewed my finding.

Subcontractors on site:

- 1. Donald P Dick
- 2. Richard Plumbing
- 3. Michael Taylor Framing
- 4. Michael Taylor Painting
- 5. JVC Masonry

# **INSPECTION ITEMS**

Documentation	
Site Contact	Satisfactory
Comment	
I had an exit meeting with Joe, and reviewed my findings in the job site .	-
Safety Program (Including IIPP)	Satisfactory
Comment	
Safety Program is available	-
Heat Illness Prevention Program	Satisfactory

Labor posters are posted	
Comment  Labor posters are posted	
Labor Law Postings	Satisfacto
Required Cal/OSHA permits have been pulled and are posted	-
Comment	
OSHA Permits	Satisfacto
Sub-Contractor Meetings	N/A
Tailgates are being conducted at least every 10 working days	-
Comment	
Tailgate Meetings	Satisfacto
Joe is conducting the daily safety inspection	-
Comment	
Daily Inspections	Satisfacto
SDS are available for employee access	-
Comment	
Safety Data Sheets	Satisfacto
Heat Illness Prevention Program is available and site specific information is completed.	-

# Emergency / Other Postings Satisfactory Comment

Emergency posters are on site and directions to nearest medical facility are posted.	-
First Aid / CPR Certification	Satisfactory
Comment	
Joe is first aid and CPR certified	-
Emergency Items	
Access / Egress	Satisfactory
Elevator for Hoisting Workers (if needed)	N/A
Fire Extinguisher(s)	Satisfactory
Comment	
Fire extinguisher is readily available in the construction trailer and some trades also have an extinguisher in there vehicle	-
First Aid Kit(s)	Satisfactory
Comment	
First Aid Kit is readily available and fully replenished	<del>-</del>
Eye Wash Station	Satisfactory
Other Fire Fighting Equipment (If needed)	N/A
General Items	
Restrooms	Satisfactory
Comment	
Restroom are cleaned and last serviced on 8/20/24	-
Hand Washing Stations	Satisfactory
Waste Containers	Satisfactory

## Potable Water Satisfactory

#### Comment

There is bottled water in the construction trailer, and also the trades have water jugs/bottles on the job construction site.



Shade	Satisfactory
Comment	
Structural shade is available	-

# Tools & Equipment

Power Tools Satisfactory

#### Comment

Air compressor and generator are safely being used. Gas containers were kept always from ignition source.



Hand Tools	Satisfactory
Comment	
Hand tools were safely used	-

#### Powder Actuated Tools N/A

Pneumatic Nailers Satisfactory
Comment

Air gun are being operated safely

#### **Mobile Elevated Work Plarforms (MEWP's)**

N/A

#### **Powered Industrial Trucks**

#### Satisfactory

#### Comment

Micheal Taylor employee was using the reach lift, he was wearing his hard hat and seat belt.



#### **Heavy Mobile Equipment (Excavators, Loaders, etc)**

N/A

#### Cranes

N/A

#### **Cylinder Storage**

N/A

#### Ladders

Satisfactory

#### Comment

Ladders were being used safely

## **Operations**

#### **Personal Protective Equipment**

**Unsatisfactor** 

#### Comment

As I walked the work site, I noticed that about half of the workers were wearing their hard hats. When I asked the others to put on their hard hats, they complied, except for a Mid Valley employee on lot 57 who refused to do so after I instructed him (see picture). Additionally, a JVC worker on lot 55 was cutting decorative rock without wearing a mask or hard hat. This issue was corrected on-site, though I was unable to take a picture.



**Impalement Hazards** 

Comment

Satisfactory

Trenching & Excavation	Satisfactory
Comment	
Open trench had danger tape around it	-
Fall Protection	N/A
Comment	
No one was working over the trigger heights that required fall Protection	-
Guardrails	N/A
Floor / Wall Openings	N/A
Supported Scaffolding	Satisfactory
Comment	
The scaffold was well put together, the access ladder has three rungs above planks, base plate nailed to mud sill	
Mobile Scaffolding	N/A
Mobile Scaffolding Suspended Scaffolding	N/A

The concrete stakes had the safety caps on



Traffic Control	N/A
Roofing Operations	N/A
Comment	
No roof operation during the safety inspection	-
Housekeeping	Satisfactory
Comment	
Good housekeeping throughout the construction site	-
Demolition	N/A
Silica Control	Unsatisfactor
Comment	
JVC worker on lot 55 was cutting decorative rock and was not using a dust mask. It was corrected on-site	-
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Unsatisfactor

Comment

A JVC worker was using a drill to mix mortar, and the power cord had been cut. He had extended it by attaching another cord from an extension cord.



Lockout / Tagout N/A

#### Stairways, Ramps, Runways

## Satisfactory

#### Comment

Stair case has the safety guards



#### Other Items (that were observed)

### Unsatisfactor

#### Comment

Tri-Valley worker is using a scaffolding A-farm stand as a ladder. He should be using a ladder instead.

