### SAFETY INSPECTION REPORT

### **CONDUCTED FOR:**

Pacific Hydrotech Corporation

#### **PROJECT:**

Well 32 - John Garthe Reservoir



# **INSPECTION TYPE:**General Construction

**INSPECTOR: JUSTYN BLANCHARD** 

DATE: NOVEMBER 27, 2024

**CITY:** SANTA ANA

STATE : CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION			
53	25	<b>0</b>	<b>28</b>
Items Inspected	Satisfactory	Unsatisfactory	N/A

A safety inspection was performed on site today on behalf of Pacific Hydrotech and it was discussed with Evelio, the foreman on site at the time of the visit. Safety is very good at the time of the visit.

- Building provides shade for the employees. Tents are also set up as needed.
- A restroom, wash station, and trash bin are all near each other.
- PPE was being worn as required. Work is being done measuring and fitting piping.
- Ladders seen on site are in good condition.
- Grinders have guards in place.
- Electricians are working in the vault. The vault is 7 feet deep and has a delineation line set. No hazards seen.

See observations below.

# **INSPECTION ITEMS**

Documentation	
Site Contact	Satisfactory
Comment	
Evelio Mondragon	-
Safety Program (Including IIPP)	Satisfactory
Comment	
Manual is on site and up to date.	-
Heat Illness Prevention Program	Satisfactory
Comment	
This is in the IIPP.	-
Safety Data Sheets	Satisfactory

**Emergency Items** 

**Access / Egress** 

**Satisfactory** 

Comment	
On site.	-
Daily Inspections	Satisfactory
Comment	
Being conducted as required.	-
Tailgate Meetings	Satisfactory
Comment	
Being conducted weekly.	-
Sub-Contractor Meetings	N/A
OSHA Permits	Satisfactory
Comment	
Trenching permit is up to date.	The production of the producti
Labor Law Postings	Satisfactory
Comment	
Labor law posters are posted on site.	-
Emergency / Other Postings	Satisfactory
First Aid / CPR Certification	Satisfactory

Elevator for Hoisting Workers (if needed)	N/A
Fire Extinguisher(s)	Satisfactory
First Aid Kit(s)	Satisfactory
Eye Wash Station	N/A
Other Fire Fighting Equipment (If needed)	N/A
General Items	
Restrooms	Satisfactory
Comment	
A restroom, trash bin and wash station is on site.	-
Hand Washing Stations	Satisfactory
Comment	
Wash station is well stocked.	-
Waste Containers	Satisfactory
Comment	
Trash bin is next to the restroom and hand wash station.	-
Potable Water	Satisfactory
Comment	
Cool water is on site for the employees.	-
Shade	Satisfactory
Comment	
Good job with shade set up for the guys near their work area. Building also provides shade.	-

## Tools & Equipment

Comment

**Power Tools** 

**Satisfactory** 

Comment	
Grinders have guards in place. Good job.	
Hand Tools	Satisfactory
Powder Actuated Tools	N/A
Pneumatic Nailers	N/A
Mobile Elevated Work Plarforms (MEWP's)	N/A
Powered Industrial Trucks	N/A
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	N/A
Ladders	Satisfactory

Ladders seen on site are in good condition.



### Operations

### **Personal Protective Equipment**

### **Satisfactory**

#### Comment

PPE was being worn as required. Work is being done measuring and fitting piping.



Trenching & Excavation	N/A
Fall Protection	N/A
Guardrails	N/A
Floor / Wall Openings	N/A
Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A

Impalement Hazards	N/A
Traffic Control	N/A
Roofing Operations	N/A
Housekeeping	Satisfactory
Comment	
Housekeeping is very good throughout the site.	-
Demolition	N/A
Silica Control	N/A
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Satisfactory
Lockout / Tagout	N/A
Stairways, Ramps, Runways	N/A
Other Items (that were observed)	Satisfactory
Comment	
Electricians are working in the vault. The vault is 7 feet deep and has a delineation line set. No hazards seen.	