

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Seaside Steel Inc.

PROJECT:
49000 Milmont



INSPECTION TYPE:
General Construction

INSPECTOR : JOSHUA JOHNSON
DATE : JULY 02, 2024
CITY : FREMONT
STATE : CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	30 Satisfactory	1 Unsatisfactory	22 N/A
------------------------------	---------------------------	----------------------------	------------------

Today I was able to perform a site inspection at the Fremont 49000 Milmont site. The slab is being poured.

The following good items were observed during the visit:

- + Plenty of water on site.
- + Shade in place.
- + The work site is clean and organized.
- + Fire extinguishers are being used.
- + Materials are being staged safely.
- + Good access/egress is in place.

Note the following violation that needs to be addressed:

Reach-lift:

- During the visit a reach-lift was being used to move a bundle of rebar. The rebar was not secured on the forks of the lift and several fell off. If another worker had been in the area, this could have been an accident. Reminders were given on-site to the operator to ensure that rebar is secured when being moved.

Carlos and his team are doing an excellent job.

•• Please see additional report notations below. •••

INSPECTION ITEMS

Documentation	
Site Contact	Satisfactory
Comment	
Carlos Garcia	-
Safety Program (Including IIPP)	Satisfactory
Comment	

Available electronically.	-
---------------------------	---

Heat Illness Prevention Program	Satisfactory
--	---------------------

Comment	
----------------	--

Available electronically.	-
---------------------------	---

Safety Data Sheets	Satisfactory
---------------------------	---------------------

Comment	
----------------	--

Available to workers.	-
-----------------------	---

Daily Inspections	Satisfactory
--------------------------	---------------------

Comment	
----------------	--

Inspections are being done.	-
-----------------------------	---

Tailgate Meetings	Satisfactory
--------------------------	---------------------

Comment	
----------------	--

Telgate meetings are being documented.	-
--	---

Sub-Contractor Meetings	N/A
--------------------------------	------------

OSHA Permits	Satisfactory
---------------------	---------------------

Labor Law Postings	Satisfactory
---------------------------	---------------------

Comment	
----------------	--

Posted on site.	-
-----------------	---


Emergency / Other Postings	Satisfactory
-----------------------------------	---------------------

Comment	
----------------	--

Posted on site.	-
-----------------	---

First Aid / CPR Certification	Satisfactory
--------------------------------------	---------------------

Emergency Items

Access / Egress		Satisfactory
Comment		
Good access and egress are in place.		

Elevator for Hoisting Workers (if needed)	N/A
--	------------

Fire Extinguisher(s)		Satisfactory
Comment		
Fire extinguishers are available on site.	-	

First Aid Kit(s)		Satisfactory
Comment		
Available in the trailer.	-	

Eye Wash Station		Satisfactory
Comment		
Available around the site.	-	

Other Fire Fighting Equipment (If needed)	N/A
--	------------

General Items

Restrooms		Satisfactory
Comment		
In place and stocked.	-	

Hand Washing Stations		Satisfactory
Comment		

In place on site.	-
-------------------	---

Waste Containers	Satisfactory
-------------------------	---------------------

Comment	
----------------	--

In place.	-
-----------	---

Potable Water	Satisfactory
----------------------	---------------------

Comment	
----------------	--

Plenty of waters available on site.	-
-------------------------------------	---

Shade	Satisfactory
--------------	---------------------

Comment	
----------------	--

Shade is available.	
---------------------	--

Tools & Equipment	
------------------------------	--

Power Tools	Satisfactory
--------------------	---------------------

Comment	
----------------	--

No concerns observed.	-
-----------------------	---

Hand Tools	Satisfactory
-------------------	---------------------

Comment	
----------------	--

No concerns observed.	-
-----------------------	---

Powder Actuated Tools	N/A
------------------------------	------------

Pneumatic Nailers	N/A
--------------------------	------------

Mobile Elevated Work Platforms (MEWP's)	N/A
--	------------

Powered Industrial Trucks	Unsatisfactory
----------------------------------	-----------------------

Comment	
What could be considered a near miss occurred while a load of rebar was being moved. See additional photos for details.	
Rebar was being distributed at different locations on the site and some fell off the bundle while it was being moved. A reminder was given on site regarding the need to make sure the load is secured before moving.	

Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
--	------------

Cranes	N/A
---------------	------------

Cylinder Storage	N/A
-------------------------	------------

Ladders	Satisfactory
----------------	---------------------

Comment	
No concerns observed.	-


Operations

Personal Protective Equipment	Satisfactory
--------------------------------------	---------------------

Comment	
Good job wearing PPE.	-

Trenching & Excavation	Satisfactory
-----------------------------------	---------------------

Comment	
----------------	--

No concerns observed. Good job having delineation lines in place.	
---	---

Fall Protection	N/A
------------------------	------------

Guardrails	N/A
-------------------	------------

Floor / Wall Openings	N/A
------------------------------	------------

Supported Scaffolding	N/A
------------------------------	------------

Mobile Scaffolding	N/A
---------------------------	------------

Suspended Scaffolding	N/A
------------------------------	------------

Confined Spaces	N/A
------------------------	------------

Impalement Hazards	Satisfactory
---------------------------	---------------------

Comment	
----------------	--

Good job having caps in place.	
--------------------------------	---

Traffic Control	Satisfactory
------------------------	---------------------

Comment	
No concerns observed.	-

Roofing Operations	N/A
---------------------------	------------

Housekeeping	Satisfactory
---------------------	---------------------

Comment	
Good organization observed.	

Demolition	N/A
-------------------	------------

Silica Control	N/A
-----------------------	------------

Rigging Operations	N/A
---------------------------	------------

Hot Work	N/A
-----------------	------------


Electrical Safety	Satisfactory
--------------------------	---------------------

Comment	
No concerns observed.	-

Lockout / Tagout	N/A
-------------------------	------------

Stairways, Ramps, Runways	Satisfactory
----------------------------------	---------------------

Comment	
No concerns observed.	-

Other Items (that were observed)	Satisfactory
Comment	
Safe parking and vehicles observed.	 A photograph showing a white pickup truck parked on a dirt lot at a construction site. The truck is viewed from the rear passenger side. In the background, there are construction materials, orange safety cones, and a clear blue sky.