

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
Seaside Steel Inc.

**PROJECT:**  
Little Dipper (Sacramento)



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** BRITTON FIELD  
**DATE :** DECEMBER 02, 2024  
**CITY :** SACRAMENTO  
**STATE :** CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

<b>53</b> Items Inspected	<b>21</b> Satisfactory	<b>3</b> Unsatisfactory	<b>29</b> N/A
------------------------------	---------------------------	----------------------------	------------------

A safety inspection was carried out on site today. I was able reviewed all safety concerns noticed on the spot with Carlos .

All documentation and paperwork for the site was filled out and kept in the Forman’s truck. Carlos has the following information:

- + Daily site inspections.
- + Weekly tailgate meeting
- + Equipment inspections

The following safety observations were made at the time of the inspection:

- + Most workers were wearing proper PPE for the task at hand. Including gloves.
- + Plenty of drinking water was provided.
- + Power saw used for cutting rebar, had face shield and hearing protection provided.
- + Restrooms were found in satisfactory condition with well stocked wash station.

Safety concerns addressed with Carlos:

- Worker performing rebar cutting was reminded to wear provided hearing protection when using power saw to cut rebar. (Raul corrected on the spot.)
- A fire extinguisher must be located nearby power saw used for rebar cutting in the event of fire. (Carlos corrected on the spot.)
- One fire extinguisher was found in satisfactory condition, but had not been inspected or documented monthly. (Carlos corrected on the spot.)

•• please see additional information below•••

# INSPECTION ITEMS

<b>Documentation</b>	
<b>Site Contact</b>	<b>Satisfactory</b>
<b>Comment</b>	

I was able to walk the site and convey all safety related observations with Carlos.	-
---	---

<b>Safety Program (Including IIPP)</b>	<b>Satisfactory</b>
--	---------------------

<b>Comment</b>
----------------

Safety Program is available	-
-----------------------------	---

<b>Heat Illness Prevention Program</b>	<b>Satisfactory</b>
--	---------------------

<b>Comment</b>
----------------


Heat Illness Prevention Program is available and site specific information is completed.	-
--	---

<b>Safety Data Sheets</b>	<b>N/A</b>
---------------------------	------------

<b>Daily Inspections</b>	<b>Satisfactory</b>
--------------------------	---------------------

<b>Comment</b>
----------------

Daily inspections are being performed
---------------------------------------




Equipment inspections are being performed daily. • Reach Lift
--

-
---

<b>Tailgate Meetings</b>	<b>Satisfactory</b>
--------------------------	---------------------

<b>Comment</b>
----------------

Tailgate meetings are being conducted each week. Sign in sheets are handed into the GC (buzz oats)
--



<b>Sub-Contractor Meetings</b>	<b>N/A</b>
--------------------------------	------------

<b>OSHA Permits</b>	<b>N/A</b>
---------------------	------------

<b>Labor Law Postings</b>	<b>Satisfactory</b>
<b>Comment</b>	
Labor law postings are located inside of site office of GYC.	-


<b>Emergency / Other Postings</b>	<b>Satisfactory</b>
<b>Comment</b>	
Hospital / urgent care route map is located inside of safety manual.	-

<b>First Aid / CPR Certification</b>	<b>Satisfactory</b>
<b>Comment</b>	
Foreman has CPR/first aid certification up-to-date.	-

## Emergency Items

<b>Access / Egress</b>	<b>Satisfactory</b>
<b>Comment</b>	
Site access is clear of obstructions and debris.	-

<b>Elevator for Hoisting Workers (if needed)</b>	<b>N/A</b>
--	------------

<b>Fire Extinguisher(s)</b>	<b>Unsatisfactory</b>
<b>Comment</b>	
Most fire extinguishers were found in satisfactory condition at the time of inspection.	-
One fire extinguisher was found in satisfactory condition. However, the extinguisher has not been inspected or documented monthly. (Carlos is correcting this.)	

<b>First Aid Kit(s)</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Eye Wash Station</b>	<b>N/A</b>
-------------------------	------------

<b>Other Fire Fighting Equipment (If needed)</b>	<b>N/A</b>
--	------------

## General Items

<b>Restrooms</b>	<b>Satisfactory</b>
------------------	---------------------

<b>Comment</b>	
Restrooms were found in satisfactory condition.	-


<b>Hand Washing Stations</b>	<b>Satisfactory</b>
------------------------------	---------------------

<b>Comment</b>	
Wash station was found in satisfactory condition. - Soap was available - Paper towels are stocked.	-

<b>Waste Containers</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Comment</b>	
Waste containers were located near restroom and active work area.	-

<b>Potable Water</b>	<b>Satisfactory</b>
----------------------	---------------------

<b>Comment</b>	
Drinking water was provided.	

<b>Shade</b>	<b>Satisfactory</b>
--------------	---------------------

<b>Comment</b>	
----------------	--

Shade on site and suitable	-
----------------------------	---

## Tools & Equipment

<b>Power Tools</b>	<b>Satisfactory</b>
--------------------	---------------------

<b>Comment</b>
----------------

Power saw was found in satisfactory condition.	
--	---

Power saw used for cutting rebar, had face shield and hearing protection provided.	-
--	---

<b>Hand Tools</b>	<b>Satisfactory</b>
-------------------	---------------------

<b>Comment</b>
----------------

All hand tools were observed and satisfactory condition.	-
--	---


<b>Powder Actuated Tools</b>	<b>N/A</b>
------------------------------	------------

<b>Pneumatic Nailers</b>	<b>N/A</b>
--------------------------	------------

<b>Mobile Elevated Work Platforms (MEWP's)</b>	<b>N/A</b>
--	------------

<b>Powered Industrial Trucks</b>	<b>Satisfactory</b>
----------------------------------	---------------------

<b>Comment</b>
----------------

Reach Lift operator was wearing seatbelt at the time of inspection.	
---	---

<b>Heavy Mobile Equipment (Excavators, Loaders, etc)</b>	<b>N/A</b>
--	------------

<b>Cranes</b>	<b>N/A</b>
---------------	------------

<b>Cylinder Storage</b>	<b>N/A</b>
-------------------------	------------

<b>Ladders</b>	<b>N/A</b>
----------------	------------


<b>Comment</b>	
No work requiring ladders was observed at the time of inspection.	-

## Operations

<b>Personal Protective Equipment</b>	<b>Unsatisfactory</b>
--------------------------------------	-----------------------

<b>Comment</b>	
----------------	--

Most workers were wearing appropriate PPE for the task at hand.	-
---	---

Worker using power saw for cutting rebar was reminded to wear hearing protection when operating cutter. (Raul corrected on the spot.)	
---	--

<b>Trenching &amp; Excavation</b>	<b>N/A</b>
-----------------------------------	------------

<b>Fall Protection</b>	<b>N/A</b>
------------------------	------------

<b>Guardrails</b>	<b>N/A</b>
-------------------	------------

<b>Floor / Wall Openings</b>	<b>Satisfactory</b>
------------------------------	---------------------

<b>Comment</b>	
----------------	--

No ground openings were observed at the time of inspection around the active work area.	-
---	---

<b>Supported Scaffolding</b>	<b>N/A</b>
<b>Mobile Scaffolding</b>	<b>N/A</b>
<b>Suspended Scaffolding</b>	<b>N/A</b>
<b>Confined Spaces</b>	<b>N/A</b>
<b>Impalement Hazards</b>	<b>Satisfactory</b>
<b>Comment</b>	
No SSI impairment hazards were observed at the time of inspection.	-
<b>Traffic Control</b>	<b>N/A</b>
<b>Comment</b>	
Traffic control was as needed. (Buzz Oats)	-
<b>Roofing Operations</b>	<b>N/A</b>
<b>Housekeeping</b>	<b>Satisfactory</b>
<b>Comment</b>	
Active work area was kept free of debris.	-
<b>Demolition</b>	<b>N/A</b>
<b>Silica Control</b>	<b>N/A</b>
<b>Comment</b>	
No silica hazard work was being performed near active work area at the time of inspection.	-
<b>Rigging Operations</b>	<b>N/A</b>
<b>Hot Work</b>	<b>Unsatisfactory</b>
<b>Comment</b>	
Fire extinguisher was needed nearby worker using power saw to cut rebar in the event of fire. (Carlos corrected on the spot.)	-



<b>Electrical Safety</b>	<b>N/A</b>
<b>Comment</b>	
No electrical safety hazards were observed at the time of inspection.	-
<b>Lockout / Tagout</b>	<b>N/A</b>
<b>Stairways, Ramps, Runways</b>	<b>N/A</b>
<b>Other Items (that were observed)</b>	<b>N/A</b>