### SAFETY INSPECTION REPORT

### **CONDUCTED FOR:**

Silverwood Landscape Construction, Inc.

PROJECT: OC Link



### **INSPECTION TYPE:**General Construction

INSPECTOR: ALEX MARTINEZ DATE: OCTOBER 29, 2024

CITY: ANAHEIM STATE: CALIFORNIA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

### SUMMARY OF INSPECTION 53 Items Inspected 30 Satisfactory Unsatisfactory N/A

Albis and his crew were observed working safely and the OC Links project. All crew members were observed wearing their required PPE. All tools and equipment were in good condition and heavy machinery was being operated compliantly.

### Safety Meeting

The crew and I had a discussion on Slips, Trips and Falls and the importance of ensuring they're keeping up with housekeeping throughout the day. All unnecessary items should always be put away and kept off working surfaces. Lastly crews were reminded to ensure they have an evacuation route at all times.

### **INSPECTION ITEMS**

# Site Contact Comment Albis Cruz was on site.

Safety Program (Including IIPP)	Satisfactory
Comment	
Available in the company vehicle	-

### Heat Illness Prevention Program Satisfactory

Safety Data Sheets	Satisfactory
Daily Inspections	Satisfactory
Tailgate Meetings	Satisfactory
Sub-Contractor Meetings	Satisfactory
OSHA Permits	N/A
Labor Law Postings	Satisfactory
Emergency / Other Postings	Satisfactory
First Aid / CPR Certification	Satisfactory

Emergency	Items
-----------	-------

Access / Egress Satisfactory

### Comment

Safe access to the work site was available.



## Elevator for Hoisting Workers (if needed) Fire Extinguisher(s) Comment Available in the company vehicle. N/A Satisfactory

First Aid Kit(s) Satisfactory

Eye Wash Station N/A

### Other Fire Fighting Equipment (If needed)

**Satisfactory** 

### General Items

Restrooms Satisfactory

### Comment

Restrooms are maintained and hand wash stations and tissue paper were available.



### **Hand Washing Stations**

**Satisfactory** 

### Waste Containers Satisfactory

### Comment

Waste bins are available around the project.



Potable Water Satisfactory

Shade Satisfactory

### Tools & Equipment

Power Tools	Satisfactory
Comment	
Power tools being used on site were observed in good condition.	-

Hand Tools Satisfactory

Powder Actuated Tools N/A

Pneumatic Nailers N/A

Mobile Elevated Work Plarforms (MEWP's)

N/A

Powered Industrial Trucks N/A

### **Heavy Mobile Equipment (Excavators, Loaders, etc)**

### **Satisfactory**

### Comment

Heavy machinery was observed being used appropriately



Cranes N/A

Cylinder Storage N/A

Ladders N/A

### Operations

**Personal Protective Equipment** 

**Satisfactory** 

Comment

All team members were observed using their required personal protective equipment.



Trenching & Excavation	Satisfactory
Fall Protection	N/A
Guardrails	N/A
Floor / Wall Openings	Satisfactory
Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Comment	
No impalement hazards were observed during the walk.	-
Traffic Control	N/A
Roofing Operations	N/A
Housekeeping	Satisfactory
Demolition	N/A

Silica Control	Satisfactory
Comment	
Water hoses were being used on site to control the dust kick up.	-
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Satisfactory
Lockout / Tagout	N/A
Stairways, Ramps, Runways	Satisfactory
Other Items (that were observed)	N/A