

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
Teserra Outdoors

**PROJECT:**  
Fish remodel



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** CHUCK HIPPENSTIEL  
**DATE :** JANUARY 13, 2025  
**CITY :** LA QUINTA  
**STATE :** CALIFORNIA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

<b>53</b> Items Inspected	<b>20</b> Satisfactory	<b>5</b> Unsatisfactory	<b>28</b> N/A
------------------------------	---------------------------	----------------------------	------------------

Foreman was Robert  
 Inspector was Chuck Hippenstiel 90955741

Overall, the job was in good clean working order. Robert was operating bobcat the time of inspection back up alarm was working. Had about six employees working in the area. They need to make sure they wear a class two safety vest as equipment is operating around them. Basic ground work and preparing for papers and concrete to be put in place.

A culture of safety and ongoing education are interdependent pillars for reducing job site accidents. Together, they foster a proactive approach to risk management, ensuring that employees are not only compliant but genuinely committed to maintaining a safe work environment. By prioritizing these elements, organizations can minimize workplace accidents, protect their workforce, and enhance overall productivity.

# INSPECTION ITEMS

Documentation	
<b>Site Contact</b>	<b>Satisfactory</b>
<b>Comment</b>	-
Adam was the foreman on site Inspector was Chuck. It was still 909-557-4108.	-
Safety Program (Including IIPP)	
<b>Comment</b>	<b>Unsatisfactory</b>
	<b>Teserra Outdoors</b>
Need to have the new IIP on site either a hard copy or electronic at all times	-
Heat Illness Prevention Program	
<b>Comment</b>	<b>Unsatisfactory</b>
	<b>Teserra Outdoors</b>
A Heat Illness Prevention Program and site specific procedures are required to be in place	-

<b>Safety Data Sheets</b>	<b>N/A</b>
---------------------------	------------

<b>Daily Inspections</b>	<b>Unsatisfactory</b>
<b>Comment</b>	<b>Teserra Outdoors</b>
Daily inspections need to be conducted.	-

<b>Tailgate Meetings</b>	<b>Satisfactory</b>
<b>Comment</b>	<b>Teserra Outdoors</b>
Tailgates are being conducted at least every 10 working days	-

<b>Sub-Contractor Meetings</b>	<b>N/A</b>
--------------------------------	------------

<b>OSHA Permits</b>	<b>N/A</b>
---------------------	------------

<b>Labor Law Postings</b>	<b>Satisfactory</b>
<b>Comment</b>	<b>Teserra Outdoors</b>
Labor law postings are in place as required.	-

<b>Emergency / Other Postings</b>	<b>Satisfactory</b>
-----------------------------------	---------------------

<b>First Aid / CPR Certification</b>	<b>Unsatisfactory</b>
<b>Comment</b>	<b>Teserra Outdoors</b>
Need to have key personnel training of first aid CPR	-

<b>Emergency Items</b>	
<b>Access / Egress</b>	<b>Satisfactory</b>
<b>Comment</b>	<b>Teressa Outdoors</b>

Availability of emergency medical service for workers on site



**Elevator for Hoisting Workers (if needed)**

**N/A**

**Fire Extinguisher(s)**

**Satisfactory**

**Comment**

**Teresa Outdoors**

Fire extinguishers located in trucks

-

**First Aid Kit(s)**

**Satisfactory**

**Comment**

**Teresa Outdoors**

Located in truck

-

**Eye Wash Station**

**Satisfactory**

**Other Fire Fighting Equipment (If needed)**

**N/A**

## General Items

**Restrooms**

**Satisfactory**

**Comment**

**Teserra Outdoors**

Plenty of toilets are located on site and are being kept clean and in good working order.

-

**Hand Washing Stations**

**Satisfactory**

**Waste Containers**

**Satisfactory**

**Potable Water**

**Satisfactory**

**Comment**

**Teserra Outdoors**

Provide clean



**Shade**

**Satisfactory**

**Comment**

**Teresa Outdoors**

Shade on site and suitable



**Tools & Equipment**

**Power Tools**

**N/A**

**Hand Tools**

**Satisfactory**

**Comment**

**Teresa Outdoors**

Tools at that time of inspection were just shovels and rakes



**Powder Actuated Tools**


**N/A**

<b>Pneumatic Nailers</b>	<b>N/A</b>
--------------------------	------------

<b>Mobile Elevated Work Platforms (MEWP's)</b>	<b>N/A</b>
--	------------

<b>Powered Industrial Trucks</b>	<b>N/A</b>
----------------------------------	------------

<b>Heavy Mobile Equipment (Excavators, Loaders, etc)</b>	<b>Satisfactory</b>
--	---------------------

<b>Comment</b>	<b>Teressa Outdoors</b>
Back alarm was working on bobcat need to make sure that operator has competent Person trained under Cal OSHA guidelines	


<b>Cranes</b>	<b>N/A</b>
---------------	------------

<b>Cylinder Storage</b>	<b>N/A</b>
-------------------------	------------

<b>Ladders</b>	<b>N/A</b>
----------------	------------

## Operations

<b>Personal Protective Equipment</b>	<b>Unsatisfactory</b>
--------------------------------------	-----------------------

<b>Comment</b>	<b>Teressa Outdoors</b>
Workers on ground need to have class two safety vest and possibly dust mask available if wind is blowing	

<b>Trenching &amp; Excavation</b>	<b>N/A</b>
-----------------------------------	------------

<b>Fall Protection</b>	<b>N/A</b>
------------------------	------------

<b>Guardrails</b>	<b>N/A</b>
-------------------	------------

<b>Floor / Wall Openings</b>	<b>N/A</b>
------------------------------	------------

<b>Supported Scaffolding</b>	<b>N/A</b>
------------------------------	------------

<b>Mobile Scaffolding</b>	<b>N/A</b>
---------------------------	------------

<b>Suspended Scaffolding</b>	<b>N/A</b>
------------------------------	------------

<b>Confined Spaces</b>	<b>N/A</b>
------------------------	------------


<b>Impalement Hazards</b>	<b>Satisfactory</b>
---------------------------	---------------------


<b>Comment</b>	<b>Teserra Outdoors</b>
Protective covers designed to cover exposed reinforced steel and other similar projections so as to prevent impalement	-

<b>Traffic Control</b>	<b>N/A</b>
------------------------	------------

<b>Roofing Operations</b>	<b>N/A</b>
---------------------------	------------

<b>Housekeeping</b>	<b>Satisfactory</b>
---------------------	---------------------

<b>Comment</b>	<b>Teressa Outdoors</b>
Housekeeping in good shape.	

<b>Demolition</b>		<b>Satisfactory</b>
<b>Comment</b>	<b>Teserra Outdoors</b>	
Silica is controlled		
<b>Silica Control</b>		<b>Satisfactory</b>
<b>Rigging Operations</b>		<b>N/A</b>
<b>Hot Work</b>		<b>N/A</b>
<b>Electrical Safety</b>		<b>Satisfactory</b>
<b>Lockout / Tagout</b>		<b>N/A</b>
<b>Stairways, Ramps, Runways</b>		<b>N/A</b>
<b>Other Items (that were observed)</b>		<b>N/A</b>