SAFETY INSPECTION REPORT

CONDUCTED FOR:

Thomas James Homes: NorCal

PROJECT:

751 17th Avenue Menlo Park



INSPECTION TYPE:

General Construction

INSPECTOR: JOSHUA JOHNSON

DATE: JUNE 12, 2024 CITY: MENLO PARK

STATE: CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION			
53 Items Inspected	29 Satisfactory	4 Unsatisfactory	20 N/A

A site inspection was carried out on-site today and I was able to walk the site and look for any safety concerns. Drywall has been installed and mud is being applied.

Note the following good items that were observed:

- + Temp electrical panel and receptacles have covers in place.
- + Fire extinguisher is on site.
- + 2024 Labor Laws are posted.
- + An eye wash station is on site.
- + Restrooms in place and stocked.
- + Waste containers are on site.
- + Handwash station is in place.

Note the following violation that needs to be addressed:

Ladder:

- Ladders missing legible safety and proper use labels. Note: A designated competent person can inspect the ladder and attach new stickers after they do an inspection to ensure the ladder is still in good condition and safe for use. Then employees can be made aware the ladder is safe to use.

Trenches:

- Unmarked trench that poses a trip or fall hazard to workers at the entrance to the site. A delineation line or cover should be used to protect workers in the area from the hazard.

Impalement Hazards:

- Nails in scrap wood. Nails should be bent over or removed to mitigate the hazard.

Stairways:

- Toe-boards missing from the top of the stairway. Toe-boards protect tools and materials from potentially falling below and striking someone. A standard toeboard shall be 4 inches (nominal) minimum in vertical height from its top edge to the level of the floor, platform, runway, or ramp. It shall be securely fastened in place and have not more than 1/4-inch clearance above floor level.
- Rails falling down around the stairway. Ensure guardrails at stairways have a top rail at 42 to 45 inches high and a mid-rail halfway. Must be capable of withstanding loads of 200lbs. The site contact was immediately informed of this issue and followed on it.

Overall, the site was found in satisfactory condition.

••• Please see additional report notations below. •••

INSPECTION ITEMS

Documentation	
Site Contact	Satisfactory
Comment	
Jamie Cruz	-
Safety Program (Including IIPP)	Satisfactory
Comment	
TJH Safety Manual/IIPP is available electronically.	-
Heat Illness Prevention Program	Satisfactory
Comment	
Available electronically.	-
Safety Data Sheets	Satisfactory
Daily Inspections	Satisfactory
Comment	
Reminder to make sure documented safety inspections are conducted every time the AM or PM stop by the site.	-
Tailgate Meetings	Satisfactory
Comment	
TJH has access to tailgate meetings and are making sure these are conducted and kept on file.	-
Sub-Contractor Meetings	Satisfactory
OSHA Permits	Satisfactory
Labor Law Postings	Satisfactory

Comment

Good job having them posted!



Emergency / Other Postings

Satisfactory

First Aid / CPR Certification	Satisfactory
Comment	
Up on the outside of the security fence	

Emergency Items	
Access / Egress	Satisfactory
Comment	
See trenching comments.	-

Elevator for Hoisting Workers (if needed)

N/A

Fire Extinguisher(s)

Satisfactory

Comment

Good job having a fire extinguisher on site.



First Aid Kit(s)	Satisfactory
Comment	

On the outside of the security fence.

Eye Wash Station Satisfactory

Comment

Available on the fence.



Other Fire Fighting Equipment (If needed)

N/A

General Items

Restrooms Satisfactory

Hand Washing Stations

Satisfactory

Comment

Great job having this in place and stocked.



Waste Contatiners	Satisfactory
Comment	
Available on site.	-

Potable Water Satisfactory

Shade Satisfactory

Tools & Equipment	
Power Tools	Satisfactory
Comment	
No concerns observed during the visit.	-
Hand Tools	Satisfactory
Comment	
No concerns observed during the visit.	-
Powder Actuated Tools	N/A
Pneumatic Nailers	N/A
Mobile Elevated Work Plarforms (MEWP's)	N/A
Powered Industrial Trucks	N/A
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	N/A
Ladders	Unsatisfactory
Comment	
Ladders missing legible labels were found on site site. See summary for additional details.	

Operations	
Personal Protective Equipment	Satisfactory
Comment	
No concerns observed.	-

Trenching & Excavation

Unsatisfactory

Comment

Unprotected trenches are found at the entrance to the site into the side of the house. This is a fall and trip hazard. See summary for additional details.



Fall Protection	Satisfactory
Comment	
See stairway for additional comments.	-
Guardrails	Satisfactory
Floor / Wall Openings	Satisfactory
Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Unsatisfactory
Comment	

Nails observed sticking out of wood debris. This can be mitigated by bending the nails over or removing them from the wood.



Traffic Control	Satisfactory
Comment	
No concerns observed.	-
Roofing Operations	N/A
Housekeeping	Satisfactory
Comment	
No concerns observed.	-
Demolition	N/A
Silica Control	N/A
Rigging Operations	N/A
Hot Work	N/A

Electrical Safety Satisfactory

Comment

Good job having all covers in place.



Lockout / Tagout N/A

Stairways, Ramps, Runways

Unsatisfactory

Comment

Guard rails around the stairway were falling down. The site contact was informed and immediately started to follow with getting these repaired.

Workers on site were informed to stay away from the stairway until it is repaired.



Other Items (that were observed)

N/A