SAFETY INSPECTION REPORT

CONDUCTED FOR: West Builders, Inc.

PROJECT: Fullerton HUB



INSPECTION TYPE: General Construction

INSPECTOR : JASON CHAVEZ DATE : NOVEMBER 27, 2024 CITY : FULLERTON STATE : CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION			
53	37	3	13
Items Inspected	Satisfactory	Unsatisfactory	N/A

The site was visited for a safety inspection. The contractors on site were observed regarding items including PPE, tools, and equipment and safe practices. Items of concern are noted in this report. The observations were discussed with the project team.

Contractors Onsite: Tinco Trademark Rye AmPam Lighthouse Glass Sharpe Atlas Hale Glass

Site Specific Activity:

Note, all trades accessing the scaffold must have a daily inspection of the scaffold. The competent person must make any corrections prior to work commencing.

Trades are engaged in rough in of plumbing and electrical. Wood and metal framing activities are in process. Insulations, drywall hanging, mudding and taping. Installing foam, plaster. Underground trenching.

INSPECTION ITEMS

Documentation	
Site Contact	Satisfactory
Comment	
Project Management Team	-
Safety Program (Including IIPP)	Satisfactory
Comment	
IIPP is available onsite.	-

Heat Illness Prevention Program	Satisfactory
Safety Data Sheets	Satisfactory
Daily Inspections	Satisfactory
Tailgate Meetings	Satisfactory
Comment	
Tailgate meetings are on file.	-
Sub-Contractor Meetings	Satisfactory
OSHA Permits	Satisfactory
Labor Law Postings	Satisfactory
Emergency / Other Postings	Satisfactory
First Aid / CPR Certification	Satisfactory
Emergency Items	
Access / Egress	Satisfactory
Elevator for Hoisting Workers (if needed)	Satisfactory
Comment	
Inspection is up to date.	-
Fire Extinguisher(s)	Satisfactory

Comment

Fire extinguishers are observed posted on the east stairway.



First Aid Kit(s)	Satisfactory
Eye Wash Station	N/A
Other Fire Fighting Equipment (If needed)	N/A
General Items	
Restrooms	Satisfactory
Hand Washing Stations	Satisfactory
Waste Containers	Satisfactory
Comment	
Waste containers were in good order.	-
Potable Water	Satisfactory
Shade	N/A
Tools & Equipment	
Power Tools	Satisfactory
Hand Tools	Satisfactory
Powder Actuated Tools	Satisfactory

Pneumatic Nailers	Satisfactory
Mobile Elevated Work Plarforms (MEWP's)	Satisfactory
Powered Industrial Trucks	Satisfactory
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	Satisfactory
Ladders	Satisfactory
Operations	
Personal Protective Equipment	Satisfactory
Comment	
Overall workers donned required PPE.	
Trenching & Excavation	N/A
Fall Protection	Satisfactory
Guardrails	Unsatisfactory
Comment	

Balconies must have guard rails. The scaffold does not qualify as a catch platform. Please ensure guard rails are maintained on balconies where necessary. Or catch platforms must be equipped with a 2x6 toe board.	
A window opening in 249 is observed with only one rail. Please ensure standard rails are setup at 42/21".	
The mezzanine section where decking is not completed (building D) should be closed off at the stair well or guard rails should be erected. No contractors may work in the area without personal fall protection.	
Please ensure the broken guard rail is fixed.	

Floor / Wall Openings

Satisfactory

Unsatisfactory

Supported Scaffolding

Comment

Satisfactory

Satisfactory

The scaffold section is missing guard rails. The ladder section should be equipped with guard rails. The erector complied to add railings throughout.



Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Traffic Control	Satisfactory
Roofing Operations	N/A

Housekeeping	Satisfactory
Comment	
Housekeeping is in good order.	
Demolition	N/A

Silica Control		

Satisfactory

Electrical Safety	Unsatisfactory
Comment	
Bulbs are missing from some light strings. Most lights are in place however please ensure these are inspected and missing bulbs are covered or replaced.	
Damaged insulation is observed on the light string extension cord. Please ensure temporary light strings are inspected.	

Lights are not powered near the hallway of 248. Please ensure all contractors maintain temporary lights.



Lockout / Tagout	N/A
Stairways, Ramps, Runways	Satisfactory
Other Items (that were observed)	N/A