# **SAFETY INSPECTION REPORT**

**CONDUCTED FOR:** West Builders, Inc.

> PROJECT: REB1



**INSPECTION TYPE:** General Construction

INSPECTOR : JUSTYN BLANCHARD DATE : OCTOBER 09, 2024 CITY : BURBANK STATE : CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

| SUMMARY OF INSPECTION |              |                |     |
|-----------------------|--------------|----------------|-----|
| 53                    | <b>34</b>    | <b>3</b>       | 16  |
| Items Inspected       | Satisfactory | Unsatisfactory | N/A |

I was able to walk the job site and review all aspects of the job site. The site was reviewed with Sean

Documentation: All required safety documentation, including the Safety Program, Safety Data Sheets, and labor law postings, were up to date and on site.

Emergency Items: Fire extinguishers were inspected monthly and found to be in good condition. First aid kits were also stocked and available.

General Site Conditions: Restrooms, hand washing stations, waste containers, and potable water were all satisfactory. The building provided adequate shade for workers.

Tools & Equipment: Power tools, hand tools, and pneumatic nailers were in good condition. Cylinder storage was compliant.

Unsatisfactory Items:

Ladders: Some ladders had worn-off labels and need replacements with legible labels.

Guardrails: The second floor had a loose upright post, and the third floor lacked proper railing. Missing or incomplete guardrails in other areas need to be installed.

Floor/Wall Openings: Some openings lacked mid-rails or guardrails. Guardrails need to be set at 42-45 inches with proper mid-rails.

Other Areas: Supported scaffolding, impalement hazards, traffic control, and electrical safety were satisfactory. Housekeeping was noted as well-maintained.

See observations of the site below.

# **INSPECTION ITEMS**

## Documentation

| Site Contact                    | Satisfactory |
|---------------------------------|--------------|
| Comment                         |              |
| Sean Coker                      | -            |
| Safety Program (Including IIPP) | Satisfactory |
| Comment                         |              |
| On site in the office.          | -            |
| Heat Illness Prevention Program | Satisfactory |
| Safety Data Sheets              | Satisfactory |
| Comment                         |              |
| On site in the office.          | -            |
| Daily Inspections               | Satisfactory |
| Comment                         |              |
| Being conducted daily.          | -            |
| Tailgate Meetings               | Satisfactory |
| Comment                         |              |
| Being conducted weekly.         | -            |
| Sub-Contractor Meetings         | Satisfactory |
| OSHA Permits                    | Satisfactory |
| Labor Law Postings              | Satisfactory |
| Comment                         |              |
| Posted in the job office.       | -            |
| Emergency / Other Postings      | Satisfactory |
| First Aid / CPR Certification   | Satisfactory |

# **Emergency Items**

### Access / Egress

### Elevator for Hoisting Workers (if needed)

# Fire Extinguisher(s)SatisfactoryCommentGood job inspecting the fire extinguishers monthly.Image: Comment of the set inguisher of the set

| First Aid Kit(s)            | Satisfactory |
|-----------------------------|--------------|
| Comment                     |              |
| In stock in the job office. | -            |
|                             |              |

### **Eye Wash Station**

| Other Fire Fighting Equipment (If needed) | Satisfactory |
|---|--------------|
| General Items                             |              |
| Restrooms                                 | Satisfactory |
| Hand Washing Stations                     | Satisfactory |
| Waste Containers                          | Satisfactory |
| Potable Water                             | Satisfactory |
| Shade                                     | Satisfactory |

Satisfactory

Satisfactory

N/A

| Comment   |              |
|---|--------------|
| Building provides shade.                          | -            |
| Tools & Equipment                                 |              |
| Power Tools                                       | Satisfactory |
| Hand Tools  | Satisfactory |
| Powder Actuated Tools                             | N/A          |
| Pneumatic Nailers                                 | Satisfactory |
| Mobile Elevated Work Plarforms (MEWP's)           | Satisfactory |
| Powered Industrial Trucks                         | N/A          |
| Heavy Mobile Equipment (Excavators, Loaders, etc) | N/A          |
| Cranes  | N/A          |
| Cylinder Storage                                  | Satisfactory |

| Cylinder Storage                           | Satisfactory |
|--|--------------|
| Comment                                    |              |
| Cylinders were seen to be stored properly. |              |

| Ladders | Unsatisfactory |
|---------|----------------|
| C       | mment          |

Gavina has a ladder near unit 623 that has worn off labels. These are not legible. Ensure all ladders on site have legible labels.



# Operations

| Personal Protective Equipment          | Satisfactory |
|--|--------------|
| Comment                                |              |
| PPE was seen being worn by the trades. | -            |
| Trenching & Excavation                 | N/A          |
|  |              |
| Fall Protection                        | N/A          |

| Guardrails  | Unsatisfactory |
|---|----------------|
| Comment   |                |
| Second floor middle upright post is loose and needs to be re-secured. |                |
| No railing is set for this section on the 3rd floor.                  |                |

| Floor / Wall Openings   | Unsatisfactory |
|---|----------------|
| Comment   |                |
| Room 215 mid rail is not set at 21"   |                |
| 315 top rail is missing. Mid rail is set at 21".  |                |
| A couple of these openings have no guardrails or only have 1. Ensure<br>these openings have guardrails at 42-45" with a mid rail. |                |
| Supported Scaffolding   | Satisfactory   |
| Mobile Scaffolding  | N/A            |
| Suspended Scaffolding   | N/A            |
| Confined Spaces   | N/A            |
| Impalement Hazards  | Satisfactory   |

Comment

| Impalement hazards are capped throughout the site.  | -            |
|---|--------------|
| Traffic Control                                     | Satisfactory |
| Roofing Operations                                  | N/A          |
| Housekeeping  | Satisfactory |
| Comment   |              |
| Good job with housekeeping throughout the site.     | -            |
| Demolition  | N/A          |
| Silica Control                                      | N/A          |
| Rigging Operations                                  | N/A          |
| Hot Work  | N/A          |
| Electrical Safety                                   | Satisfactory |
| Comment   |              |
| Electrical cables were seen to be in good condition | -            |
| Lockout / Tagout                                    | N/A          |

| Stairways, Ramps, Runways  | Satisfactory |
|--|--------------|
| Comment  |              |
| Good job keeping walkways clean and securing drywall stored in hallways. |              |

| Other Items (that were observed)  | Satisfactory |
|---|--------------|
| Comment   |              |
| Water extinguisher in the stairwell is not charged properly and does not have a pin in place. |              |