SAFETY INSPECTION REPORT

CONDUCTED FOR:

West Builders, Inc.

PROJECT: REH



INSPECTION TYPE:General Construction

INSPECTOR: JASON CHAVEZ DATE: AUGUST 14, 2024 CITY: LOS ANGELES

STATE: CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

Satisfactory

SUMMARY OF INSPECTION				
53	32	12	9	
Items Inspected	Satisfactory	Unsatisfactory	N/A	

The site was visited for a safety inspection. The contractors on site were observed regarding items including PPE, tools, and equipment and safe practices. Items of concern are noted in this report. The observations were discussed with the superintendent.

Contractors Onsite:

JDI

Gavina

Conco

Wiss

JLM Steel

Site Specific Activity:

- +Glass Installation
- +Mechanical Rough in
- +Plumbing Rough in
- +Metal stud framing / Drywall

Heat Illness Prevention Program

+Roofing Activities

INSPECTION ITEMS

Documentation	
Site Contact	Satisfactory
Comment	
Brian and Lucas Management team	-
Safety Program (Including IIPP)	Satisfactory
Comment	
IIPP is onsite and available.	-

Comment	
HIPP is onsite and available inside the IIPP	-
Safety Data Sheets	Satisfactory
Daily Inspections	Satisfactory
Tailgate Meetings	Satisfactory
Sub-Contractor Meetings	N/A
OSHA Permits	Satisfactory
Labor Law Postings	Satisfactory
Emergency / Other Postings	Satisfactory
First Aid / CPR Certification	Satisfactory
Emergency Items	
Access / Egress	Unsatisfactory
Comment	

Comment

The stairway is missing some lighting. Please ensure access lighting is maintained through the project.



Elevator for Hoisting Workers (if needed)

Satisfactory

Fire Extinguisher(s) **Satisfactory**

Comment

Fire extinguishers are placed as needed.	-
First Aid Kit(s)	Satisfactory
Eye Wash Station	Satisfactory
Other Fire Fighting Equipment (If needed)	N/A
General Items	
Restrooms	Satisfactory
Hand Washing Stations	Satisfactory
Waste Containers	Satisfactory
Potable Water	Satisfactory
Shade	Satisfactory
Tools & Equipment	
Power Tools	Satisfactory
Hand Tools	Satisfactory
Powder Actuated Tools	Satisfactory
Comment	
Signage is posted.	-
Pneumatic Nailers	N/A
Mobile Elevated Work Plarforms (MEWP's)	Satisfactory
Powered Industrial Trucks	Unsatisfactory
Comment	

The lift mast must be lowered when the lift is parked. Forks should be flush on the ground. The lift should not be left with a load engaged on the forks. Reported to the management team.



Heavy Mobile Equipment (Excavators, Loaders, etc)

N/A

Cranes N/A

Cylinder Storage Unsatisfactory

Comment

A cylinder is observed on the roof deck not protected from tipping or falling. Please ensure all cylinders are properly secured.



Ladders Unsatisfactory

Comment

A leaned A frame ladder is observed on the upper deck. This should not be used as an access ladder over the parapet wall. A properly setup extension ladder should be secured at a 4:1 ratio and extend 36" above the parapet. It may be met with another extension ladder on the other side or large A frame that is opened, locked, leveled and secured from tipping or falling. Discussed with management team.



Operations

Personal Protective Equipment

Unsatisfactory

Comment

Gavina worker is cutting metal studs without safety glasses or a face shield. The worker complied to don appropriate PPE.



Trenching & Excavation

Satisfactory

Fall Protection Satisfactory

Guardrails Unsatisfactory

Comment

The elevator has the rails removed. The scaffold inside is 12" away from the platform. The opening should maintain guard rails to protect workers.



Red tape does not serve as fall protection. A guard rail should be posted here.



Floor / Wall Openings

Satisfactory

Supported Scaffolding

Satisfactory

Mobile Scaffolding

N/A

Suspended Scaffolding

N/A

Confined Spaces

Unsatisfactory

Comment

Confined spaces should be controlled and identified. Contractors must follow their confined space program determining if the space is permit required or not.



Impalement Hazards

Unsatisfactory

Comment

Multiple rebar below 72" from the grade must be protected with osha approved caps. Reported to the superintendent.



Traffic Control

Satisfactory

Roofing Operations

Satisfactory

Housekeeping

Unsatisfactory

Comment

Contractor trash has accumulated. MC cable is in the walkway. This debris should be removed.



Debris and materials are blocking the access way. The materials should be cleared from access ways and trash disposed of.



Demolition N/A

Silica Control Unsatisfactory

Comment

A worker is grinding concrete without any engineering controls such as a vacuum or water. Silica dust must be co trolled at all times. The worker was notified of the violation. In addition he needs a guard on the grinder. All reported to the management team.





Rigging Operations

Satisfactory

Hot Work

Satisfactory

Electrical Safety

Unsatisfactory

Comment

The temporary power cord has broken insulation at the end of the cord. This should be removed.



Lockout / Tagout

N/A

Stairways, Ramps, Runways

Satisfactory

Other Items (that were observed)

Unsatisfactory

Comment

Cords should be secured from becoming trip hazards.

