SAFETY INSPECTION REPORT

CONDUCTED FOR:

Woodside Homes: Arizona

PROJECT:

Icon at Thunderbird



INSPECTION TYPE:

General Construction

INSPECTOR: SEAN NELSON **DATE**: DECEMBER 18, 2024

CITY: GLENDALE STATE: AZ

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION				
54 Items Inspected	26 Satisfactory	5 Unsatisfactory	23 N/A	

A safety site inspection was conducted today

- + All paperwork and postings were up to date.
- + Safety center checklist was posted, but half of the sheet has disappeared and has not yet been replaced
- + The fire extinguisher inside of the safety center has not been inspected for December

Subcontracting trades on site at time of inspection are as follows:

- *Aztec Lighting
- *Desert Royal Painting

The following safety issues were observed:

- The majority of the issues on this site were with the scaffolding, the issues were as follows: Scaffolding guardrails were removed and never replaced, the guardrails for the scaffolding are part of the structure
- All sections of the scaffolding must be fully planked Bad planks must be removed from the scaffold platform

Should setup a 2x4 in areas where fall over six feet may occur

- + There was plenty of water found on site
- + Site superintendent was able to address all safety concerns

INSPECTION ITEMS Documentation Site Contact Safety Program (Including IIPP) Satisfactory Heat Illness Prevention Program Satisfactory

Safety Data Sheets

Satisfactory

Daily Inspections

Unsatisfactory

Comment

Half of the safety center checklist has disappeared and has not yet been updated.



Tailgate Meetings

Satisfactory

Sub-Contractor Meetings

Satisfactory

OSHA Permits

Satisfactory

Labor Law Postings

Satisfactory

Emergency / Other Postings

Satisfactory

First Aid / CPR Certification

Satisfactory

Emergency Items

Access / Egress

Satisfactory

Elevator for Hoisting Workers (if needed)

N/A

Fire Extinguisher(s)

Unsatisfactory

Comment

Hand Tools

Satisfactory

The fire extinguisher inside of the safety center has not yet been inspected for December.



First Aid Kit(s)	Satisfactory
Eye Wash Station	Satisfactory
Personnel Hoist	N/A
Other Fire Fighting Equipment (If needed)	N/A
General Items	
Restrooms	Satisfactory
Hand Washing Stations	Unsatisfactory
Comment	
No hand washing station has yet been setup for this job site	-
Waste Containers	Satisfactory
Potable Water	Satisfactory
Shade	Satisfactory
Tools & Equipment	
Power Tools	Satisfactory

Powder Actuated Tools	N/A
Pneumatic Nailers	N/A
Mobile Elevated Work Plarforms (MEWP's)	N/A
Powered Industrial Trucks	N/A
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	N/A
Ladders	Satisfactory

$\overline{}$	
	perations
-	

Personal Protective Equipment

N/A

Trenching & Excavation

N/A

Fall Protection Unsatisfactory

Comment

All areas where fall greater than six feet can occur should be addressed.



Guardrails Satisfactory Comment

Guardrails have been setup inside of every two story home.



Floor / Wall Openings

Satisfactory

Unsatisfactory

Supported Scaffolding

Comment

There should be guardrails on the scaffolding to prevent roof access without fall protection.



Guardrails should never be removed from the scaffolding, the guardrails are apart of the scaffolding structure.



Bad planks should be removed from the scaffolding platform.



All sections of scaffolding should be fully planked and there should be no gaps greater than an inch in between planks.



Mobile Scaffolding	N/A

Suspended Scaffolding N/A

Confined Spaces N/A

Impalement Hazards Satisfactory

Comment

All impalement hazards were secured.



Roofing Operations N/A

Housekeeping Satisfactory

Demolition N/A

Silica Control N/A

Rigging Operations N/A

Hot Work	N/A
Electrical Safety	Satisfactory
Lockout / Tagout	N/A
Stairways, Ramps, Runways	Satisfactory
Other Items (that were observed)	N/A