#### SAFETY INSPECTION REPORT

#### **CONDUCTED FOR:**

**Woodside Homes** 

#### **PROJECT:**

The Park @ Granite Bay



#### **INSPECTION TYPE:**

**General Construction** 

**INSPECTOR: MARTIN RODRIGUEZ** 

DATE: AUGUST 28, 2024 CITY: GRANITE BAY STATE: CALIFORNIA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION			
53	30	2	<b>21</b>
Items Inspected	Satisfactory	Unsatisfactory	N/A

Arrived on-site and began my safety inspection. Weather conditions are sunny with clear skies and temperatures in the 100's there is plenty of water on site for workers. There is plenty of shade available for all personnel. Restrooms are clean and serviced regularly. Hand wash stations are full and serviced frequently. All required PPE is being worn by workers.

Hand too,s are in good condition and being used correctly. Power tools are in good working condition and are being used safely. Pneumatic nailers are being used safely. Air compressors are bled frequently. Forklift is being operated safely. Electrical equipment and cords are in good condition and protected from being damaged. Fall protection is being worn as required at trigger heights. Excellent work.

The following safety items were nor]ted and require attention:

- 1) Lot 36: Scaffold at roof presents a fall hazard at the end of the scaffold and roof. Guardrails are needed on the inside of the scaffold.
- 2) Lot 36: Scaffold erected inside home needs guard rails at second level and has to single planks used for access at second floor level. Planks need to be removed and not used, as it is not adequate to protect from falls.
- 3) Worker is standing on second to last rung on a-frame ladder. Asked worker not to stand on last rung to top of ladder. Corrected immediately.

#### **INSPECTION ITEMS**

Documentation	
Site Contact	Satisfactory
Comment	
Tim Parish (Superintendent)	-
Safety Program (Including IIPP)	Satisfactory

Safety Program (Including IIPP)	Satisfactory
Comment	
IIPP is available in the project office.	-

Heat Illness Prevention Program	Satisfactory
---------------------------------	--------------

Comment	
HIPA program is available in the project office.	-

Safety Data Sheets	Satisfactory
Comment	
SDS's are on file.	-

Daily Inspections	Satisfactory
Comment	
Inspections are being completed.	-

Tailgate Meetings	Satisfactory
Comment	
Safety meetings are being completed.	-

Sub-Contractor Meetings	Satisfactory
Comment	
Safety meetings are being completed.	-

OSHA Permits	Satisfactory
Comment	
Permits are on file.	-

## Permits are on file. Labor Law Postings Satisfactory

Labor postings are posted in office.



#### Emergency / Other Postings

Comment

**Satisfactory** 

#### Comment

Elegance information is available in the office.



## First Aid / CPR Certification Comment Certificates are on file. Satisfactory -

#### **Emergency Items**

#### Access / Egress Satisfactory

#### Comment

Acces/egress is maintained.



#### **Elevator for Hoisting Workers (if needed)**

N/A

#### Fire Extinguisher(s) Satisfactory

#### Comment

Fire extinguisher is charged.



#### First Aid Kit(s) Satisfactory

#### Comment

First aid kit is in office.



#### Eye Wash Station Satisfactory

#### Other Fire Fighting Equipment (If needed)

N/A

#### **General Items**

#### Restrooms Satisfactory

#### Comment

Restrooms are serviced regularly.



#### **Hand Washing Stations**

**Satisfactory** 

#### Comment

Wash stations are available.



Waste Containers	Satisfactory
Comment	
Waste containers are available.	-

Potable Water	Satisfactory
Comment	
There is water on site.	-

### Shade Satisfactory Comment

Shade is available for workers.



Tools & Equipment	
Power Tools	Satisfactory
Comment	
Power tools are in good condition.	-

Hand Tools	Satisfactory
------------	--------------

Comment	
Hand tools are in good condition.	-

#### Powder Actuated Tools N/A

Pneumatic Nailers	Satisfactory
Comment	
Nailers are being used safely.	-

#### Mobile Elevated Work Plarforms (MEWP's) N/A

#### Powered Industrial Trucks N/A

#### Heavy Mobile Equipment (Excavators, Loaders, etc) N/A

ı	Cranes	N/A

#### Cylinder Storage N/A

#### Ladders Unsatisfactory

#### Comment

Worker is standing on second to last rung on a-frame ladder. Asked worker not to stand on last rung to top of ladder. Corrected immediately.



# Operations Personal Protective Equipment Satisfactory Comment PPE is being worn.

#### **Trenching & Excavation**

N/A

#### Fall Protection Satisfactory

#### Comment

Fall protection is being worn.



#### **Guardrails** Satisfactory

#### Comment

Guardrails are in place.



#### Floor / Wall Openings N/A

#### **Supported Scaffolding**

**Unsatisfactory** 

#### Comment

Lot 36: Scaffold at roof presents a fall hazard at the end of the scaffold and roof. Guardrails are needed on the inside of the scaffold.



Scaffold erected inside home needs guard rails at second level and has to single planks used for access at second floor level. Planks need to be removed and not used, as it is not adequate to protect from falls.



Suspended Scaffolding N/A	
Confined Spaces N/A	
Impalement Hazards N/A	
Traffic Control N/A	
Traffic Control N/A	

#### Housekeeping Satisfactory

#### Comment

Housekeeping is maintained.

**Roofing Operations** 



**Satisfactory** 

Demolition	N/A
Silica Control	N/A
Rigging Operations	N/A

Hot Work N/A

Electrical Safety Satisfactory

Comment

Electrical equipment is good.

Lockout / Tagout N/A

#### Stairways, Ramps, Runways

#### **Satisfactory**

#### Comment

Stairways are in place.



Other Items (that were observed)

N/A