



JOB HAZARD ANALYSIS

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Concrete North, Inc.	Project	21-035 River Islands K-8
Date	May 19, 2022	PREPARED BY	rgonzalez@concretenorth.net
Task	stripping forms		

Work Steps	Potential Hazards	Control Methods
Strip Forms at Columns and Curbs. Mix and Dry Pack Grout at Door openings at Trash Containment Area. Clean up around job site. Housekeeping all work areas. 1) Pack materials for required tasks. 2) Rollout tools and equipment to preform required tasks. Keep all areas clean and clear of clutter. Continue to follow COVID-19 Safety protocol. Stretch and Flex Review Whiteboard during morning huddle. Rollout tools and equipment. Keep all areas clean and clear of clutter. Gather all materials used and unused and stack neatly. Gather all tools and cords and equipment to store.	Over stretch or muscle strain. Slips trips and falls Uneven surfaces. Power tools. Shock hazard. Loud noise. Flying debris. Heavy lifting. Heat stress. Exposed rebar. Pinch points Concrete splatter Concrete Burn Other trades.	Stretch before work and as needed. Always use a clear path of travel. Watch your step and be focused and alert at all times. Handle all power tools properly. Inspect all tools and cords and equipment before use. Use proper ear protection for required task. Use proper eye and face protection for required task. Use you legs. Get help when needed. Keep yourself hydrated and keep an eye on the person nearby watch for signs of dehydration. Avoid walking between machinery and always be aware of your surroundings. Place only OSHA approved rebar caps. Maintain good communication with everyone.

Signature :