



# ACCIDENT/ INCIDENT INVESTIGATION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Concrete North, Inc.	<b>Project</b>	23-010 Capitol Annex
<b>Date of Incident</b>	September 30, 2024	<b>Time of Incident</b>	10:58 AM
<b>Date of Investigation</b>	September 30, 2024	<b>Time of Investigation</b>	05:15 AM
<b>Investigator</b>	Hilario Ruiz	<b>Type of Incident</b>	Injury

## EMPLOYEE INFORMATION

**Employee Name**  
Juan Aguirre

**Nature Of Injury**  
knack box falling

## DESCRIPTION OF INCIDENT

Juan Aguirre was installing his knee pads behind the knack box when another employee Gerardo Mercado opened the box all the way up making the shocks break and the knack box flip backwards with the weight of its own door hitting Juan Aguirre. Hitting him lightly in his right rib, causing him a scratch in the rib. Foremen Hilario Ruiz and Oswaldo Solaris quickly approach to see what had happened. Hilario talked to Juan to see if he was ok. Juan said he was fine and wanted to go back to work, however, Hilario after talking to superintendent Woody decided to send Juan to his house to rest for the day. Later on the day Hilario kept checking with Juan by calling him every 2-3 hours. Everytime he check in with Juan responded to be fine and ready to go back to work.

## WITNESSES & STATEMENTS

Name	Company	Statement
Oswaldo Solorio	CNI	Witness states that the knack box door broke the shock holding the door in place making the knack box to flip backwards and hitting Juan Aguirre in the right side of his rib cage. Leaving a scratch on the right rib side.

## COMMENTS & PHOTOS

**comment**

**Image**

## ROOT CAUSE

Older knack box.

## CONTRIBUTING FACTORS

Not paying attention from employees. Being complacent.

## INVESTIGATOR SIGNATURE

A handwritten signature in black ink, appearing to be "John P. V.", written in a cursive style.

## CORRECTIVE ACTION

Remove box out of use and check others for similar issues.

## ADDITIONAL INFORMATION

None