

EER.INC

safety and procedure on shot blasting
of concrete floors

step(1) all EER.INC) equipment is inspected
in house when coming and
leaving (EER.INC) warehouse by in house
tech and mechanic

step(2) when arriving to job site we un-load
and stage equipment and power
source in job site work area.

step(3) equipment set up in designated

area and power cable is run to generator for equipment to be powered up for job work to begin.

step(4)all (EER.INC) worker are at all times to have on all (PPE)at all jobsites

and tape work area off from the public from entering at some job sites that are open to public access

safety glasses are required at all times on theses jobs by anyone in the area of our equipment.

step(5) when job is complete our machine is broke down and cleaned all debris is bagged up at jobsite

all (EER.INC) worker that shot blast for our have anywhere from 10 to 15 year of hands

on experience of shot blasting each for
(EER.INC)