



JOB HAZARD ANALYSIS

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	EER, Inc.	Project	shop eer inc
Date	December 08, 2022	PREPARED BY	joe@eerent.com
Task	shot blasting		

Work Steps	Potential Hazards	Control Methods
Walk job with supervisor on job set up equipment and power source. Make sure everything is caution taped off only ER workers allowed.	Potential hazard is slip and fall, and I injury from flying debris from machine	All workers wearing proper PPE and not letting anyone in area. One machine is running that doesn't belong there.

Signature :