

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Helio	Type of Inspection:	SCC USE ONLY: General Contractor Review
Project	Arya	Date of Inspection	May 30, 2023
Inspector Name	Jeremy Chavez	Time of Inspection	09:42 AM

INSPECTION ITEMS

Item		Comment	Photo
Safety Manual	Satisfactory		-
Tailgate Meetings	Satisfactory		-
SDS	Satisfactory		-
Daily Inspection	Satisfactory	Good job performing and documenting the daily job site inspection.	
Sub-Contractor Meetings	N/A		-
Labor Law Posters	Satisfactory	Labor Laws are posted.	-
Codes/Emergency Posters	Satisfactory	Emergency Evacuation Map is posted. Emergency numbers and driving directions are posted. General codes are posted.	-
Permits	N/A		-
Fire Extinguisher	Satisfactory		-
Building Fire Extinguisher	Satisfactory		-
First Aid Kit	Satisfactory		-
First Aid/CPR Cert	Satisfactory		-
Restrooms/Wash Stations	Satisfactory	Restrooms and wash stations observed were maintained according to regulatory standards.	
Waste Containers	Satisfactory	Waste containers observed were maintained according to regulatory standards.	-
Water Supply	N/A		-

Shade	Satisfactory	Shade observed was maintained according to regulatory standards.	-
Power Tools	Satisfactory		-
Hand Tools	Satisfactory		-
Power Saws	N/A		-
Personal Protective Equipment	Satisfactory	Employees were observed wearing the required PPE for their task.	
Electrical Safety	Satisfactory	Good job providing illumination where required. This had been an ongoing issue that was corrected.	
Trenching/Excavation	N/A		-
Confined Space	N/A		-
Fall Protection	N/A		-
Ladder Safety	Satisfactory		-
Access/Egress	Satisfactory		-
Stairway/Ramps/Runways	Satisfactory		-
Heavy Equipment	N/A		-
Crane/Rigging	N/A		-
Powder Actuated Tools	N/A		-
Cylinder Storage	N/A		-
Floor/Roof/Wall Openings	N/A		-
Railing	Unsatisfactory		-
Material Storage	Unsatisfactory		-
Impalement Hazards	Satisfactory		-
Traffic Control	N/A		-
Scissor Lifts/Boom Lift	N/A		-
Powered Industrial Trucks	Satisfactory	Safe work practices were observed while employees were using equipment.	
Scaffolding/Shoring	Satisfactory		-
Suspended Scaffolding	N/A		-
Silica Items/Dust	N/A		-
Hot Work	N/A		-

Housekeeping	Satisfactory	Excellent job with housekeeping throughout the project.		
Roofing Operations	N/A		-	
Demolition	N/A		-	

UNSATISFACTORY ITEMS

Photo	Comment	Corrective Action
	Guardrails are installed at an inadequate height. Please ensure railing is installed at 42-45" top rail, with a mid rail halfway between the top rail and the working platform.	
	Plywood is stacked along a wall and has not been secured from tipping, slipping, or falling. Please ensure materials are secured.	