# SAFETY INSPECTION REPORT

### **CONDUCTED FOR:**

**Graham Prewett** 

#### **PROJECT:**

Fresno Airport



# **INSPECTION TYPE:**

**General Construction** 

**INSPECTOR: FRANCISCO ROMERO** 

**DATE:** JANUARY 01, 2025

CITY: FRESNO STATE: CALIFORNIA

SITE CONTACT: GABINO VIDRIO ADDITIONAL SITE CONTACT: N/A

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION			
52	29	0	23
Items Inspected	Satisfactory	Unsatisfactory	N/A

At my arrival, I met Gabino on site. We inspected for paperwork completeness and everything was in order.

Documents reviewed

**IPP** 

first aid kit

Fire extinguisher

PPE

After we went to the roof and we met Jorge and his crew. , we inspected the workers and everyone was wearing all their PPE. I also verified tools.

Tools verified on the roof:

Fall protection devices

PPE

Extension cords

All workers were following

# **INSPECTION ITEMS**

Documentation	
Safety Program (Including IIPP)	Satisfactory
Comment	graham Prewett
Met Gabino on site and we walked the site together	-
Heat Illness Prevention Program	Satisfactory

Comment

Heat Illness Prevention Program is available and site specific information is completed.



Safety Data Sheets	N/A
Daily Inspections	Satisfactory
Tailgate Meetings	Satisfactory
Sub-Contractor Meetings	N/A
OSHA Permits	N/A
Labor Law Postings	N/A
Emergency / Other Postings	Satisfactory
First Aid / CPR Certification	Satisfactory
Emergency Items	
Access / Egress	Satisfactory
Comment	-
Availability of emergency medical service for workers on site	-
Elevator for Hoisting Workers (if needed)	N/A
Fire Extinguisher(s)	Satisfactory
Comment	-

ABC fire extinguisher inspected once a month and once a year by a company



First Aid Kit(s)	Satisfactory
Comment	<u>-</u>
First aid kit were verified on site	Surefill Control of the Program  FIRST AID  10 SERIES  72 PECES  SUPPLICATO ALL  FICA Repaired * Cata ALLOW  FICA Repaired * Cata ALLOW  RECORD

Eye Wash Station	Satisfactory
Comment	-
Eye wash on site and is current	-

Other Fire Fighting Equipment (If needed)	N/A
---	-----

Other Fire Fighting Equipment (If needed)	N/A
General Items	
Restrooms	Satisfactory
Hand Washing Stations	Satisfactory
Waste Containers	Satisfactory
Potable Water	Satisfactory

Shade	Satisfactory
Tools & Equipment	
Power Tools	Satisfactory
Comment	-
All power tools and equipment in good functional order	-
Hand Tools	Satisfactory
Powder Actuated Tools	N/A
Pneumatic Nailers	N/A
Mobile Elevated Work Plarforms (MEWP's)	N/A
Powered Industrial Trucks	N/A
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	N/A
Ladders	Satisfactory
Operations	
Personal Protective Equipment	Satisfactory
Comment	-

All PPE being worn



## **Trenching & Excavation**

N/A

## Fall Protection Satisfactory

Comment

Fall protection as to trade in place



# Guardrails Satisfactory

Comment

Guardrails need to have the top rail installed at 42-45\" and a mid-rail at half the height of the top rail. Upright supports are needed every 8 feet.



### Floor / Wall Openings

Satisfactory

**Supported Scaffolding** 

N/A

Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Traffic Control	Satisfactory
Comment	-
Traffic control applied as to city plan	-
Roofing Operations	Satisfactory
Comment	-
Fall protection / skylights are protected	-
Housekeeping	Satisfactory
Demolition	N/A
Silica Control	N/A
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Satisfactory
Lockout / Tagout	Satisfactory
Stairways, Ramps, Runways	Satisfactory
Comment	•
Temporary handrails are in place at 34-38\" above the tread nosing on all stairways. \\\"	-

Other Items (that were observed)

N/A