

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

| Company | Karsyn Construction | Type of Inspection: | Scaffolding |
|----------------|---------------------|-----------------------|------------------|
| Project | Selma roof access | Date of Inspection | January 30, 2025 |
| Inspector Name | Rodolfo Breceda | Time of Inspection | 07:44 AM |

| NOTES | | | | | | | |
|-----------------|--------------|----------------|-----|--|--|--|--|
| 15 | 15 | 0 | 0 | | | | |
| Items Inspected | Satisfactory | Unsatisfactory | N/A | | | | |

INSPECTION ITEMS

| General | |
|---|--------------|
| Are daily inspections being done by a competent person? | Satisfactory |
| Is the scaffold on a secure foundation? | Satisfactory |
| Are base plates installed and appropriately nailed to mud sills (if sills are required)? | Satisfactory |
| s the scaffold plumb and level? | Satisfactory |
| Are cross braces installed per the manufacturer and OSHA instructions? | Satisfactory |
| Are platforms fully planked with no more than a 1" gap between planks? | Satisfactory |
| Are planks in safe condition? | Satisfactory |
| Do planks overlap supports (or otherwise secured) per manufacturer and OSHA instructions? | Satisfactory |

| Are guardrails correctly installed on platforms above 6 feet? (Note: Some Mfg's require rails at any height) | Satisfactory |
|---|--------------|
| is there safe access to each working level of the scaffold? | Satisfactory |
| Are toe-boards installed where required, including above entranceways and where others may pass underneath? | Satisfactory |
| if more than four times the width of the base, is the scaffold braced per the manufacturer and OSHA instructions? | Satisfactory |
| Are only trained users being allowed on the scaffold? | Satisfactory |
| Are only competent, qualified persons erecting and dismantling scaffolding? | Satisfactory |
| Is the scaffold safe to use in every other way? | Satisfactory |