

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Teserra Outdoors

PROJECT:
Fish remodel



INSPECTION TYPE:
General Construction

INSPECTOR : CHUCK HIPPENSTIEL
DATE : JANUARY 13, 2025
CITY : LA QUINTA
STATE : CALIFORNIA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	21 Satisfactory	3 Unsatisfactory	29 N/A
------------------------------	---------------------------	----------------------------	------------------

Foreman was Robert
 Inspector was Chuck Hippenstiel 90955741

Overall, job site was unfairly good shape talked with employees regarding safety safety requirements. Robert felt he was getting the support he needed from the office guys working around bobcat. Need to make sure they are wearing class two safety vest as industrial equipment are moving. As pool is be put in the backyard, Things are very tight a lot of workers in the backyard at the time of inspection. Make sure that they are aware of equipment moving around and the bobcat operator is aware of people walking.

A culture of safety and ongoing education are interdependent pillars for reducing job site accidents. Together, they foster a proactive approach to risk management, ensuring that employees are not only compliant but genuinely committed to maintaining a safe work environment. By prioritizing these elements, organizations can minimize workplace accidents, protect their workforce, and enhance overall productivity.

INSPECTION ITEMS

Documentation	
Site Contact	Satisfactory
Comment	-
Robert was the foreman on site Inspector was Chuck Hippenstiel 909-557-4108.	-
Safety Program (Including IIPP)	Satisfactory
Comment	Teserra Outdoors
Need to have the new IIP on site either a hard copy or electronic at all times	-
Heat Illness Prevention Program	Satisfactory
Comment	Teserra Outdoors

A Heat Illness Prevention Program and site specific procedures are required to be in place	-
--	---

Safety Data Sheets	N/A
---------------------------	------------

Daily Inspections	Unsatisfactory
--------------------------	-----------------------

Comment	Teserra Outdoors
Daily inspections need to be conducted.	-

Tailgate Meetings	Satisfactory
--------------------------	---------------------

Comment	Teserra Outdoors
Tailgates are being conducted at least every 10 working days	-

Sub-Contractor Meetings	N/A
--------------------------------	------------

OSHA Permits	N/A
---------------------	------------

Labor Law Postings	Satisfactory
---------------------------	---------------------

Comment	Teserra Outdoors
Labor law postings are in place as required.	-

Emergency / Other Postings	Satisfactory
-----------------------------------	---------------------

First Aid / CPR Certification	Unsatisfactory
--------------------------------------	-----------------------

Comment	Teserra Outdoors
Need to have key personnel training of first aid CPR	-

Emergency Items

Access / Egress	Satisfactory
------------------------	---------------------

Comment	Teserra Outdoors
----------------	-------------------------

Availability of emergency medical service for workers on site



Elevator for Hoisting Workers (if needed)

N/A

Fire Extinguisher(s)

Satisfactory

Comment

Teserra Outdoors

Fire extinguisher the first aid kit was located in truck. Need to make sure at least quarterly. They are being inspected.



First Aid Kit(s)

Satisfactory

Comment

Teserra Outdoors

First aid kit was located in truck, we talked to the foreman of employees are to take or use the first aid kit. They are to report it to the foreman.



Eye Wash Station

Satisfactory

Other Fire Fighting Equipment (If needed)

N/A

General Items


Restrooms Satisfactory

Comment	Teserra Outdoors
Plenty of toilets are located on site and are being kept clean and in good working order.	-

Hand Washing Stations Satisfactory

Waste Containers Satisfactory

Potable Water Satisfactory

Comment	Teserra Outdoors
Provide clean	

Shade Satisfactory

Comment	Teserra Outdoors
Shade on site and suitable	

Tools & Equipment

Power Tools N/A

Hand Tools	Satisfactory
-------------------	---------------------

Comment	Teserra Outdoors
Basic use where a handpick and a shovel	

Powder Actuated Tools	N/A
------------------------------	------------

Pneumatic Nailers	N/A
--------------------------	------------

Mobile Elevated Work Platforms (MEWP's)	N/A
--	------------

Powered Industrial Trucks	N/A
----------------------------------	------------

Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
--	------------

Cranes	N/A
---------------	------------

Cylinder Storage	N/A
-------------------------	------------

Ladders	N/A
----------------	------------

Operations	
-------------------	--

Personal Protective Equipment	Unsatisfactory
--------------------------------------	-----------------------

Comment	Teserra Outdoors
---------	------------------

Workers should be wearing eye protection as they are breaking up concrete tiles and large amount of dust to occur. Dust mass should be applied.



Trenching & Excavation	N/A
-----------------------------------	------------

Fall Protection	N/A
------------------------	------------

Guardrails	N/A
-------------------	------------

Floor / Wall Openings	N/A
------------------------------	------------

Supported Scaffolding	N/A
------------------------------	------------

Mobile Scaffolding	N/A
---------------------------	------------

Suspended Scaffolding	N/A
------------------------------	------------

Confined Spaces	N/A
------------------------	------------

Impalement Hazards	Satisfactory
---------------------------	---------------------

Comment	Teserra Outdoors
Protective covers designed to cover exposed reinforced steel and other similar projections so as to prevent impalement	-

Traffic Control	N/A
------------------------	------------

Roofing Operations	N/A
---------------------------	------------

Housekeeping	Satisfactory
---------------------	---------------------

Comment	Teserra Outdoors
----------------	-------------------------

Housekeeping in good shape.



Demolition	Satisfactory
-------------------	---------------------

Comment	Teserra Outdoors
----------------	-------------------------

Silica is controlled



Silica Control	Satisfactory
-----------------------	---------------------

Rigging Operations	N/A
---------------------------	------------

Hot Work	N/A
-----------------	------------

Electrical Safety	Satisfactory
--------------------------	---------------------

Lockout / Tagout	N/A
-------------------------	------------

Stairways, Ramps, Runways	N/A
----------------------------------	------------

Other Items (that were observed)	N/A
---	------------