SAFETY INSPECTION REPORT

CONDUCTED FOR: UC Construction

PROJECT:

Euclid Apartments



INSPECTION TYPE: General Construction

INSPECTOR : JORDAN DELOYE DATE : JANUARY 07, 2025 CITY : NATIONAL CITY STATE : CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION			
54	24	6	24
Items Inspected	Satisfactory	Unsatisfactory	N/A

The job site was reviewed with Ismael Cruz. We were able to discuss all aspects of the job as well as all safety concerns that were noticed on site. Note the following:

1. **Impalement Hazards**: Please ensure that caps are placed over all bolts in pads and metal stakes that present impalement hazards

2. **Trenching**: One trench that sits up against a 7' bank should be approved by a professional engineer assuring that it's safe to work around.

3. **PPE**: Please make sure that workers are keeping their hard hats on.

INSPECTION ITEMS

Documentation	
Site Contact	Satisfactory
Comment	
Reviewed the site with Stan.	-
Safety Program (Including IIPP)	Satisfactory
Comment	
Safety Program is available	-
Heat Illness Prevention Program	Satisfactory
Comment	
Heat Illness Prevention Program is available and site specific information is completed.	-
Safety Data Sheets	Satisfactory

Comment

-

SDS are available for employee access

Daily Inspections

Daily Inspections	Satisfactory
Comment	
Daily inspections are being performed	

Tailgate Meetings	Satisfactory
Comment	
Tailgates are being conducted at least every 10 working days	-

Sub-Contractor Meetings	Satisfactory
Comment	
Sub contractors are performing their tailgate meetings at least every 10 working days	

OSHA Permits	Unsatisfactory
Comment	-
Please post Osha Trenching Permit in the office	-

Labor Law Postings		Satisfactory
	Comment	

Unsatisfactory

Labor law postings are in place as required.

Emergency / Other Postings	Satisfactory
Comment	
Emergency posters are on site and directions to nearest medical facility are posted.	
First Aid / CPR Certification	Satisfactory
Emergency Items	
Access / Egress	Satisfactory
Elevator for Hoisting Workers (if needed)	N/A

Fire	Exting	uisher	(s)
1 11 0	LAUNG	aistici	3

Comment

N/A

Satisfactory

Fire extinguisher is not current and not up-to-date



First Aid Kit(s)	Satisfactory
Comment	
Located in the office	FIRST AID KIT

Eye Wash Station		Satisfactory
	Comment	
Located in the office		-

Other Fire Fighting Equipment (If needed)

General Items

Restrooms

Comment



Comment On site and stocked Image: Comment of the stocked	Hand Washing Stations	Satisfactory
On site and stocked	Comment	
	On site and stocked	

Waste Containers	Satisfactory
Comment	
Waste containers provided	-

Potable Water	Satisfactory
Comment	
Provided bottled water	

Shade

Satisfactory

Satisfactory

Comment

Shade on site and suitable

Tools & Equipment

Power Tools

Comment

All power tools and equipment in good functional order



-

Hand Tools	Satisfactory
Powder Actuated Tools	N/A
Pneumatic Nailers	N/A
Mobile Elevated Work Plarforms (MEWP's)	N/A
Powered Industrial Trucks	Satisfactory
Comment	
Equipment inspected daily	-
Heavy Mobile Equipment (Excavators, Loaders, etc)	Satisfactory
Comment	
Heavy Equipment inspected daily	-
Cranes	N/A

Cylinder Storage	N/A

Ladders

Operations

Personal Protective Equipment

Comment

Some of the concrete workers were not wearing their hard hats.



Trenching & Excavation

Comment

One trench that sits up against a 7' bank should be approved by a professional engineer assuring that it's safe to work around. Any excavation 5' or deeper must have a protective system in place. If that is not possible, a professional engineer needs to be consulted to ensure it is safe to work around. This excavation is 7'



Fall Protection	N/A
Guardrails	N/A
Floor / Wall Openings	N/A
Supported Scaffolding	N/A
	N//A
Mobile Scaffolding	N/A

N/A

Unsatisfactory

Unsatisfactory

Unsatisfactory

Suspended Scaffolding	N/A
Confined Spaces	N/A

Impalement Hazards Comment Please ensure that caps are placed over all bolts in pads that present impalement hazards



Comment

Please make sure that protective caps are covering all metal stakes that present an impalement hazard.



Traffic Control

Comment

Traffic control applied as to city plan



Roofing Operations

N/A

Satisfactory

Housekeeping	Satisfactory
Comment	
Housekeeping in good shape.	-
Demolition	N/A
Silica Control	N/A
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	N/A
Lockout / Tagout	N/A
Stairways, Ramps, Runways	N/A
Other Items (that were observed)	N/A