SAFETY INSPECTION REPORT

CONDUCTED FOR: West Builders, Inc.

> PROJECT: REB1



INSPECTION TYPE: General Construction

INSPECTOR : JUSTYN BLANCHARD DATE : JUNE 21, 2024 CITY : BURBANK STATE : CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

Standing Framing Jordan Drywall - AIM Steel

Gavina Plumbing

Work on Site:

SUMMARY OF INSPECTION			
53 Items Inspected	34 Satisfactory	3 Unsatisfactory	16 N/A
Contractors viewed on Site: - CEC			

- Scaffolding is seen to be erected properly and tied off where required. Good job.

- Jordan Drywall employees were seen using mobile scaffolds and ladders safely.

Jordan Drywall workers were seen using a power tools safely and has the required PPE on.
Standard framing employee was reminded to wear safety glasses when using nail guns.

- Gavina employees were seen operating scissor lifts safely.

- Great job with securing the wall openings throughout the building.

- Ladder on L5 needs to extend 3 feet past the landing platform.

- L3 to L4 ladder is secured and extends 3 feet past the landing platform.

- Fall protection is in place for the framers on the roof. Yo-yo's are set up.

Comment

- Impalement hazards are capped throughout the site.

- Excellent job with toe boards throughout the site.

- Railing on the roof is 36". Railing must be 42".

INSPECTION ITEMS

- Railing for L6 stairwell needs to be set at 21" and 42". Also there are protruding nails sticking out that is an

Satisfactory

Sean Coker

Site Contact

impalement hazard.

Documentation

Safety Program (Including IIPP)

Satisfactory

-

Comment	
On site in the office.	-
Heat Illness Prevention Program	Satisfactory
Safety Data Sheets	Satisfactory
Comment	
On site in the office.	-
Daily Inspections	Satisfactory
Comment	
Being conducted daily.	-
Tailgate Meetings	Satisfactory
Comment	
Being conducted weekly.	
Sub-Contractor Meetings	Satisfactory
OSHA Permits	Satisfactory
Labor Law Postings	Satisfactory
Comment	
Posted in the job office.	-
Emergency / Other Postings	Satisfactory
First Aid / CPR Certification	Satisfactory
Emergency Items	
	Satisfactory
Access / Egress	-


Fire Extinguisher(s)	Satisfactory
Comment	·
Fire extinguisher seen on site are up-to-date	-
	Catiofactory
First Aid Kit(s)	Satisfactory
Comment In stock in the job office.	_
	-
Eye Wash Station	N/A
Other Fire Fighting Equipment (If needed)	N/A
General Items	
Restrooms	Satisfactory
Hand Washing Stations	Satisfactory
Waste Containers	Satisfactory
Potable Water	Satisfactory
Shade	Satisfactory
Comment	
Good job with setting up shade on the roof as temperatures reach over 80°.	

Tools & Equipment

Power Tools

Satisfactory

Comment	
Jordan Drywall workers were seen using a power tools safely and has the required PPE on.	
Hand Tools	Satisfactory
Powder Actuated Tools	N/A
Pneumatic Nailers	Satisfactory
Mobile Elevated Work Plarforms (MEWP's)	Satisfactory
Comment	
Gavina employees were seen operating scissor lifts safely.	
Powered Industrial Trucks	N/A
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	N/A
Ladders	Unsatisfactory
Comment	



Operations

Personal Protective Equipment

Comment

Standard framing employee was reminded to wear safety glasses when using nail guns.

Unsatisfactory



Trenching & Excavation

N/A

Fall Protection	Satisfactory
Comment	
Fall protection is in place on the roof for the framers.	
Guardrails	Unsatisfactory
Comment	
Excellent job with toe boards throughout the site.	
Railing for L6 stairwell needs to be set at 21" and 42". Also there are protruding nails sticking out that is an impalement hazard.	
Railing on the roof is 36". Railing must be 42".	

Floor / Wall Openings	Satisfactory
Comment	
Great job with securing the wall openings throughout the building.	

Supported Scaffolding	Satisfactory
Comment	
Scaffolding is seen to be erected properly and tied off where required. Good job.	

Mobile Scaffolding	Satisfactory
Comment	
Jordan Drywall employees were seen using mobile scaffolds and ladders safely.	
Suspended Scaffolding	N/A

Confined Spaces	N/A

Impalement Hazards	Satisfactory
Comment	
Impalement hazards are capped throughout the site.	
Traffic Control	Satisfactory
Roofing Operations	N/A
Housekeeping	Satisfactory
Comment	
Good job with housekeeping throughout the site.	-
Demolition	N/A
Silica Control	N/A
Rigging Operations	N/A
Hot Work	Satisfactory
Electrical Safety	Satisfactory
Lockout / Tagout	N/A
Stairways, Ramps, Runways	Satisfactory
Other Items (that were observed)	N/A