## **SAFETY INSPECTION REPORT**

**CONDUCTED FOR:** W.L. Butler Construction, Inc.

## **PROJECT:**

Fountaingrove Apartments



**INSPECTION TYPE:** General Construction

INSPECTOR : JOSHUA JOHNSON DATE : JANUARY 16, 2025 CITY : SANTA ROSA STATE : CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs



A site inspection was carried out on-site today. The project is progressing well with interior finish work is being completed on the upper buildings of the site. The framing for the E building is moving higher. D building interior and exterior work is ongoing. F building framing work is moving forward.

Note the following good items that were observed:

- + Fire extinguishers and first aid kits are on site.
- + MEWPs with manuals.
- + Reach lift operated safely.
- + Restrooms available.
- + Handwashing stations available.

The following concern was observed:

#### **Pneumatic Nailers**

- A nail gun was left unattended and plugged into a air compressor. Manufacturer instructions require these be un-plugged from an air source when they are unattended. Cal/Osha indicates the following: "Safety training shall be conducted prior to initial assignment to operate pneumatically-driven nailers or staplers. Refresher training shall be provided to the operator when: The operator has been observed using the pneumatically-driven nailer or stapler in an unsafe manner." This training should be verified.

#### Impalement Hazard

- Anchors pose an impalement hazard. Ensure protection is in place.

- Note: Cal Osha mentions the following: "Protection from Reinforcing Steel and Other Similar Projections. (1) Employees working at grade or at the same surface as exposed protruding reinforcing steel or other similar projections, shall be protected against the hazard of impalement by guarding all exposed ends that extend up to 6 feet above grade or other work surface, with protective covers, or troughs.

Overall, the site was found in satisfactory condition.

ooo Please see additional report notations below. ooo

## **INSPECTION ITEMS**

Documentation	
Site Contact	Satisfactory
Comment	
Miguel Castaneda	-
Safety Program (Including IIPP)	Satisfactory
Comment	
Good job having this available on site.	-
Heat Illness Prevention Program	Satisfactory
Comment	
Good job having this available on site.	-
Safety Data Sheets	Satisfactory
Comment	
Good job having this available on site.	-
Daily Inspections	Satisfactory
Comment	
Ensure these are performed and documented every day.	-
Tailgate Meetings	Satisfactory
Comment	
Being performed.	-
Sub-Contractor Meetings	Satisfactory
OSHA Permits	Satisfactory
Comment	
Good job having these permits in place.	-

Satisfactory

N/A

-

Labor Law Postings	Satisfactory
Comment	
Good job having these posted. NOTE: 2025 posters will be needed.	-

## Emergency / Other Postings Comment

Good job having these posted in the office.

First Aid / CPR Certification	Satisfactory
Comment	
Ensure these are up to date. Typically certification is required every 2 years.	-

## Emergency Items

Fire Extinguisher(s)

	isfactory
Comment -	
No concerns observed	

### Elevator for Hoisting Workers (if needed)

	Satisfactory
Comment	-
uisher located by a das powered air	

Good job having a fire extinguisher located by a gas powered air compressor.



First Aid Kit(s)	Satisfactory
Comment	
Available.	-

N/A

Satisfactory

Eye Wash Station	Satisfactory
Comment	
In place.	-

## **Other Fire Fighting Equipment (If needed)**

## General Items

### Restrooms

#### Comment

Plenty of toilets are located on site and are being kept clean and in good working order.



\_

Hand Washing Stations	Satisfactory
Comment	
Ensure stations are stocked with hand towels	-
Ensure stations are stocked with hand towels	-

Waste Containers	Satisfactory
Comment	
Good job having dumpsters and waste containers in place.	-

Potable Water		Satisfactory
Con	iment	
Available.		-
Shade		Satisfactory
Con	nment	
Provided by the building.		-

Tools & Equipment	
Power Tools	Satisfactory
Comment	-
Guards observed in place.	-
Hand Tools	Satisfactory
Comment	
No concerns observed.	-
Powder Actuated Tools	N/A

Pneumatic Nailers	Unsatisfactory
Comment	Ciarra
Nails guns need to be disconnected from compressed air when not in use	

Mobile Elevated Work Plarforms (MEWP's)	Satisfactory
Comment	-
Parked safely.	-
Powered Industrial Trucks	Satisfactory

-

Comment

Satisfactory

**Satisfactory** 

Observed parked safely.



Heavy Mobile Equipment (Excavators, Loaders, etc)	Satisfactory
Comment	
No concerns observed.	-
Cranes	N/A
Cylinder Storage	Satisfactory
Comment	
Good job ensuring propane cylinders are stored safely.	<u>-</u>

Good job ensuring propane cylinders are stored safely.

Ladders

Comment

No concerns observed.

## Operations

#### **Personal Protective Equipment**

Comment

Clear signage regarding expected PPE is in place. A few reminders were given on site.

-

-

\_

Transhing 9 Fusewation	Catiofactory
Trenching & Excavation	Satisfactory
Fall Protection	Satisfactory
Comment	-
No concerns observed.	-
Guardrails	Satisfactory
Floor / Wall Openings	Satisfactory
Comment	
Ensure all chases and floor/roof openings are well protected.	-
Supported Scaffolding	Satisfactory
Comment	-
No concerns observed.	-
Mobile Scaffolding	Satisfactory
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Unsatisfactory
Comment	Ciarra
Ensure anchor bolts are capped. Some on the top level of the E building were observed missing protection. Site contact is following.	
Comment	BT Roofing

Ensure anchor bracket has protection over it. Most hazards have protection in place. However, this one located on the D building is missing protection.



Traffic Control	Satisfactory
Roofing Operations	Satisfactory
Housekeeping	Satisfactory
Comment	-
Housekeeping in good shape.	-
Demolition	N/A
Silica Control	Satisfactory
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Satisfactory
Comment	-

Good job identifying powerlines.



### Lockout / Tagout

Stairways, Ramps, Runways

# Other Items (that were observed) Comment Good job ensuring drywall is secured.

## Satisfactory

Satisfactory

Satisfactory

