SAFETY INSPECTION REPORT

CONDUCTED FOR:

Woodside Homes: Arizona

PROJECT:

Horizon at the Dells



INSPECTION TYPE:

General Construction

INSPECTOR: SEAN NELSON

DATE: JULY 24, 2024

CITY:

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected

Satisfactory

7 Unsatisfactory **20** N/A

There were a few issues with the scaffolding on site. The safety checklist was posted, it has not been filled out since January. The fire extinguisher inside of the office hasn't been inspected in months. Painters need to wear fall protection when painting on the roofs.

INSPECTION ITEMS

Documentation

Site Contact Satisfactory

Safety Program (Including IIPP)
Satisfactory

Heat Illness Prevention Program Satisfactory

Safety Data Sheets Satisfactory

Daily Inspections Unsatisfactory

Comment

The safety checklist hasn't been filled out since January.



Tailgate Meetings Satisfactory

Sub-Contractor Meetings Satisfactory

N/A

OSHA Permits Satisfactory

Labor Law Postings Satisfactory

Emergency / Other Postings Satisfactory

First Aid / CPR Certification Satisfactory

Emergency Items

Access / Egress Satisfactory

Elevator for Hoisting Workers (if needed)

Fire Extinguisher(s) Unsatisfactory

Comment

The fire extinguisher inside of the safety center hasn't been inspected since January.



First Aid Kit(s) Satisfactory

Eye Wash Station Satisfactory

Other Fire Fighting Equipment (If needed)

N/A

General Items

Restrooms Satisfactory

Hand Washing Stations Unsatisfactory

Comment	
No hand washing station has yet been setup for this job site	-
Vaste Containers	Satisfactory
Potable Water	Satisfactory
Shade	Satisfactory
ools & Equipment	
Power Tools	Satisfactory
land Tools	Satisfactory
Powder Actuated Tools	N/A
Pneumatic Nailers	Satisfactory
Mobile Elevated Work Plarforms (MEWP's)	N/A
Powered Industrial Trucks	N/A
leavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	N/A
adders	Satisfactory
Operations	
Personal Protective Equipment	Unsatisfactor

There were a few Framers on site that were wearing tennis shoes.



Trenching & Excavation

Unsatisfactory

Comment

All open trenches on site must be barricaded.



Fall Protection Unsatisfactory

Comment

The painters were working on the roof without wearing any fall protection.



Guardrails N/A

Floor / Wall Openings N/A

Supported Scaffolding Unsatisfactory

Comment

Bad planks must not be used for the supported platform.	
All sections of scaffolding must have a ladder access.	
There should be no gaps greater than an inch in between planks.	
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Traffic Control	Satisfactory
Roofing Operations	N/A

Housekeeping	Satisfactory
Demolition	N/A
Silica Control	Satisfactory
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Satisfactory
Lockout / Tagout	N/A
Stairways, Ramps, Runways	N/A
Other Items (that were observed)	N/A