SAFETY INSPECTION REPORT

CONDUCTED FOR:

Woodside Homes: Arizona

PROJECT:

Horizon at the Dells



INSPECTION TYPE:

General Construction

INSPECTOR: SEAN NELSON DATE: AUGUST 21, 2024

CITY:

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION 53 Items Inspected 7 Unsatisfactory N/A

A safety site inspection was conducted today. I was able to review all safety concerns with

- + All paperwork and postings were up to date.
- + Safety center checklist was posted

Subcontracting trades on site at time of inspection are as follows:

- ••
- *

The following safety issues were observed:

- -
- -
- -
- -
- _
- + There was plenty of water found on site
- + Overall, the site was found in satisfactory condition
- + Site superintendent was able to address all safety concerns

INSPECTION ITEMS

Documentation

Site Contact Satisfactory

Safety Program (Including IIPP)

Satisfactory

Fire Extinguisher(s)

Comment

Unsatisfactory

Heat Illness Prevention Program Satisfactory **Safety Data Sheets** Satisfactory **Daily Inspections** Unsatisfactory Comment The safety checklist has been posted and filled out for July, but not yet for August. **Tailgate Meetings** Satisfactory **Sub-Contractor Meetings** Satisfactory **OSHA Permits** Satisfactory **Labor Law Postings** Satisfactory **Emergency / Other Postings** Satisfactory First Aid / CPR Certification Satisfactory **Emergency Items Access / Egress** Satisfactory **Elevator for Hoisting Workers (if needed)** N/A

The fire extinguisher inside of the safety center hasn't been inspected since January.



Roofers were using flammable gases and liquids, but did not have a fire extinguisher within 25 feet of those materials.



First Aid Kit(s)	Satisfactory

Eye Wash Station Satisfactory

Other Fire Fighting Equipment (If needed)

N/A

General Items

Restrooms Satisfactory

Hand Washing Stations	Unsatisfactory
Comment	
No hand washing station has yet been setup for this job site	-

Waste Containers Satisfactory

Potable Water Satisfactory

Shade Satisfactory

Tools & Equipment

Power Tools Satisfactory

Hand Tools Satisfactory

Powder Actuated Tools N/A

Pneumatic Nailers Satisfactory

Mobile Elevated Work Plarforms (MEWP's)

N/A

Powered Industrial Trucks N/A

Heavy Mobile Equipment (Excavators, Loaders, etc)

N/A

Cranes N/A

Cylinder Storage N/A

Ladders Unsatisfactory

Comment

All ladders used for access must be tied off and extend three feet over the leading edge.



Operations

Personal Protective Equipment

Unsatisfactory

Comment

The roofers weren't wearing any fall protection.



Trenching & Excavation

N/A

Fall Protection Unsatisfactory

Comment

The roofers didn't even have any fall protection on the roof with them. Everyone must be tied off when working above six feet in height.



Guardrails N/A

Floor / Wall Openings N/A

Supported Scaffolding

Unsatisfactory

Comment

All sections of scaffolding must have a ladder access.



Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Traffic Control	Satisfactory
Roofing Operations	N/A
Housekeeping	Satisfactory
Demolition	N/A
Silica Control	Satisfactory
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Satisfactory
Lockout / Tagout	N/A
Stairways, Ramps, Runways	N/A
Other Items (that were observed)	N/A