SAFETY INSPECTION REPORT

CONDUCTED FOR: Woodside Homes: Arizona

PROJECT:

Overlook at the Dells



INSPECTION TYPE: General Construction

INSPECTOR : SEAN NELSON DATE : OCTOBER 22, 2024 CITY : PRESCOTT STATE : ARIZONA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION 53 22 24 N/A Unsatisfactory Items Inspected Satisfactory

A safety site inspection was conducted today.

- + The safety center was setup, IIPP was accessible
- + Safety center checklist was posted, but is not up to date

Subcontracting trades on site at time of inspection are as follows: *McDermott Construction

*Austin Electric

*Aspire Construction Group

The following safety issues were observed:

- Framers had broken hard hats on site
- Need to inspect electrical cords daily
- Most of the scaffolding on site were missing ladders accesses
- Need to inspect scaffolding before use
- Scaffold erectors just red tagged all scaffold sections
- Most sections of the scaffolding on site were not fully planked
- The safety checklist was posted but not being filled out
- The fire extinguisher inside of the safety center has not yet been inspected for October
- All open trenches must be barricaded
- + There was plenty of water found on site
- + These issues were noticed by Andrew as well

INSPECTION ITEMS

Documentation

Site Contact

Safety Program (Including IIPP)

Page 2 of 8

Satisfactory

Satisfactory

Satisfactory

Heat Illness Prevention Program	Satisfactory

Safety Data Sheets

Daily Inspections	Unsatisfactory
Comment	
The safety checklist was posted but has not been filled out since July.	
Failgate Meetings	Satisfactory

Sub-Contractor Meetings	Satisfactory
OSHA Permits	Satisfactory
Labor Law Postings	Satisfactory
Emergency / Other Postings	Satisfactory
First Aid / CPR Certification	Satisfactory

Emergency Items	
Access / Egress	Satisfactory
Elevator for Hoisting Workers (if needed)	N/A
Fire Extinguisher(s)	Unsatisfactory
Comment	

Satisfactory

The fire extinguisher inside of the safety center has not yet been inspected for October.



First Aid Kit(s)

Eye Wash Station Satisfactory Comment An eyewash station has been setup. N/A

Other Fire Fighting Equipment (If needed)

General Items	
Restrooms	Satisfactory
Hand Washing Stations	Unsatisfactory
Comment	
No hand washing station has yet been setup for this job site	-
Waste Containers	Satisfactory
Potable Water	Satisfactory
Shade	Satisfactory

Tools & Equipment	
Power Tools	Satisfactory
Hand Tools	Satisfactory
Powder Actuated Tools	N/A
Pneumatic Nailers	N/A
Mobile Elevated Work Plarforms (MEWP's)	N/A
Powered Industrial Trucks	N/A
Heavy Mobile Equipment (Excavators, Loaders, etc)	Satisfactory
Cranes	N/A
Cylinder Storage	N/A
Ladders	Satisfactory
Operations	

Personal Protective Equipment	Unsatisfactory
Comment	
Framers were using broken hard hats.	

Trenching & Excavation

Unsatisfactory

All open trenches must be barricaded.

Comment



Fall Protection	N/A
Guardrails	N/A
Floor / Wall Openings	N/A
Supported Scaffolding	Unsatisfactory

Comment	
All sections of scaffolding must have a ladder access, inspection tag and end rails.	
All sections of scaffolding must be fully planked and have end rails.	

Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Traffic Control	Satisfactory
Roofing Operations	N/A
Housekeeping	Satisfactory
Demolition	N/A
Silica Control	N/A
Rigging Operations	N/A
Hot Work	N/A

Electrical Safety	Unsatisfactory
Comment	
We found a frayed cord being used. They replaced it immediately.	SERTICE 109

Lockout / Tagout	N/A
Stairways, Ramps, Runways	N/A