# SAFETY INSPECTION REPORT

# **CONDUCTED FOR:**

Woodside Homes: Arizona

# **PROJECT:**

Palo Verde at North Creek



# **INSPECTION TYPE:**

**General Construction** 

INSPECTOR: SEAN NELSON DATE: OCTOBER 21, 2024 CITY: QUEENS CREEK

**STATE**: AZ

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION			
53 Items Inspected	<b>26</b> Satisfactory	<b>6</b> Unsatisfactory	<b>21</b> N/A

A safety site inspection was conducted today

- + All paperwork and postings were up to date.
- + Safety center checklist was posted but has not yet been filled out for October

Subcontracting trades on site at time of inspection are as follows:

- \*Austin Electric
- \*Desert Vista
- \*Saddleback Roofing
- \*Younger Bros Plumbing
- \*Austin Companies

**Aztec Lighting** 

The following safety issues were observed:

- Stucco workers weren't wearing their hard hats
- Fire extinguishers on site must be inspected monthly
- Must barricade open trenches
- There were several issues with the scaffolding on site, such as: missing planks, missing inspection tags, missing ladder access, missing end rails and missing guardrails
- + There was plenty of water found on site
- + The safety issues were addressed with the site superintendent

# Documentation Site Contact Safety Program (Including IIPP) Satisfactory Heat Illness Prevention Program Satisfactory

# **Safety Data Sheets**

# Satisfactory

# **Daily Inspections**

# Unsatisfactory

### Comment

The safety checklist has been posted, but has not yet been filled out for October



# **Tailgate Meetings**

# Satisfactory

# **Sub-Contractor Meetings**

# Satisfactory

### **OSHA Permits**

# Satisfactory

# **Labor Law Postings**

# Satisfactory

### Comment

The OSHA posters have been setup.



# **Emergency / Other Postings**

# Satisfactory

# First Aid / CPR Certification

# Satisfactory

# **Emergency Items**

Access / Egress Satisfactory

**Elevator for Hoisting Workers (if needed)** 

N/A

Fire Extinguisher(s)

Unsatisfactory

Comment

The fire extinguisher on site is not being inspected monthly.



First Aid Kit(s) Satisfactory

Eye Wash Station Satisfactory

Other Fire Fighting Equipment (If needed)

N/A

General Items

Restrooms Satisfactory

Hand Washing Stations

**Unsatisfactory** 

Comment

No hand washing station has yet been setup for this job site

Waste Containers Satisfactory

Potable Water Satisfactory

Shade Satisfactory

Tools & Equipment

Power Tools	Satisfactory

Hand Tools Satisfactory

Powder Actuated Tools N/A

Pneumatic Nailers Satisfactory

Mobile Elevated Work Plarforms (MEWP's)

N/A

Powered Industrial Trucks N/A

Heavy Mobile Equipment (Excavators, Loaders, etc)

N/A

Cranes N/A

Cylinder Storage N/A

Ladders Satisfactory

# **Operations**

# **Personal Protective Equipment**

Unsatisfactory

# Comment

The stucco workers were not wearing their hard hats.



# **Trenching & Excavation**

Unsatisfactory

Comment

Need to make sure that all open trenches are barricaded or need to setup an open trench sign.



Fall Protection N/A

Guardrails N/A

Floor / Wall Openings N/A

# Supported Scaffolding

# **Unsatisfactory**

### Comment

All sections of scaffolding must have an inspection tag and must have a ladder access and guardrails.



All sections of scaffolding must be fully planked and there should never be any gaps greater than an inch in between planks.



Single planks used on scaffolding is prohibited. Must have a minimum of three planks .



Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Traffic Control	Satisfactory
Roofing Operations	N/A
Housekeeping	Satisfactory
Demolition	N/A
Silica Control	Satisfactory
	Satisfactory
Rigging Operations	N/A
Rigging Operations  Hot Work	·
	N/A
Hot Work	N/A

Other Items (that were observed)

N/A