

## **HOT WORK PERMIT**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Pacific Hydrotech Corporation	Project	C2304 2401 N. Bristol
Start Time	07:40 AM	Finish Time	02:00 PM
Person Filling Out	Chuck Erickson	Fire Watch Person	Antonio Estanislao
End Fire Watch Time	02:30 PM	Work Location	CENTRATE excavator
Add Date	June 13, 2024		

=> Person doing hot work has been trained in the safe use of equipment, and how to work safely

## **QUESTIONS**

- => Fire extinguishers available for immediate use
- => Correct type fire extinguishers are available
- => Combustible materials and supplies are moved away from the hot work location (at least 35')
- => Verify that equipment is not to be used near flammable vapors or liquids, or their containers
- => Fire hazards that can't be moved are protected by appropriate guards
- => On-site contractors and personnel advised of hot work
- => Maintain a fire watch during operations and for at least 30 minutes after work has been completed

## **SIGNATURE**

