



Builder Link® Trade Performance by Project For The Past 90 Days

Performance Rating Scale: 1 - 3 Unacceptable, 4 - 7 Acceptable, 8 - 10 Excellent

**Project: Arbor Gates**

Trade Performance	Company Name	Trade Assignment
10.0	Superintendent	Concrete Footings
10.0	Superintendent	Concrete Forming
10.0	Superintendent	Concrete Reinforcement
10.0	Superintendent	Concrete Waterproofing
10.0	Superintendent	Plumbing
10.0	Superintendent	Roofing

**Project: Bella Vista II**

Trade Performance	Company Name	Trade Assignment
10.0	Superintendent	Door Installation
8.7	Superintendent	Electrical
10.0	Superintendent	Exterior Cladding
10.0	Superintendent	Fire Sprinkler
10.0	Superintendent	Framing
8.9	Superintendent	HVAC
10.0	Superintendent	Lath Vendor
10.0	Superintendent	Lathing/Plastering
9.0	Superintendent	Plumbing
10.0	Superintendent	Roofing
10.0	Superintendent	Weather Resistive Barrier
7.8	Superintendent	Window Installation

**Project: Bonterra II**

Trade Performance	Company Name	Trade Assignment
10.0	Superintendent	Concrete Forming
10.0	Superintendent	Door Installation
10.0	Superintendent	Electrical

**Quality Built® The Next Generation of Quality Assurance®**

633 S. Andrews Ave. Suite 204, Fort Lauderdale, FL 33301 800.547.5125

Email: [customerservice@qualitybuilt.com](mailto:customerservice@qualitybuilt.com)

10.0	Superintendent	Exterior Cladding
10.0	Superintendent	Fire Sprinkler
10.0	Superintendent	Framing
9.3	Superintendent	HVAC
10.0	Superintendent	Lath Vendor
10.0	Superintendent	Lathing/Plastering
8.2	Superintendent	Plumbing
10.0	Superintendent	Roofing
10.0	Superintendent	Weather Resistive Barrier
9.3	Superintendent	Window Installation
9.5	Superintendent	Wood Framing

**Project: Cypress Park Ph 2 - QA has no data at this time**

Trade Performance	Company Name	Trade Assignment
-------------------	--------------	------------------

**Project: Cypress Park Ph3 - GDR has no data at this time**

Trade Performance	Company Name	Trade Assignment
-------------------	--------------	------------------

**Project: Hidden Oaks**

Trade Performance	Company Name	Trade Assignment
10.0	Superintendent	Electrical
10.0	Superintendent	Exterior Cladding
10.0	Superintendent	Fire Sprinkler
9.5	Superintendent	HVAC
10.0	Superintendent	Lath Vendor
10.0	Superintendent	Lathing/Plastering
8.2	Superintendent	Plumbing
9.1	Superintendent	Roofing
10.0	Superintendent	Weather Resistive Barrier
8.4	Superintendent	Wood Framing

**Project: Kensington II**

Trade Performance	Company Name	Trade Assignment
10.0	Superintendent	Door Installation

**Quality Built® The Next Generation of Quality Assurance®**

633 S. Andrews Ave. Suite 204, Fort Lauderdale, FL 33301 800.547.5125

Email: [customerservice@qualitybuilt.com](mailto:customerservice@qualitybuilt.com)

9.1	Superintendent	Electrical
10.0	Superintendent	Exterior Cladding
10.0	Superintendent	Fire Sprinkler
10.0	Superintendent	Framing
9.5	Superintendent	HVAC
10.0	Superintendent	Lath Vendor
9.1	Superintendent	Lathing/Plastering
8.4	Superintendent	Plumbing
10.0	Superintendent	Roofing
10.0	Superintendent	Superintendent
8.7	Superintendent	Weather Resistive Barrier
9.3	Superintendent	Window Installation
9.8	Superintendent	Wood Framing

**Project: Maplewood - GDR has no data at this time**

Trade Performance	Company Name	Trade Assignment
-------------------	--------------	------------------

**Project: Quail Run Ph II**

Trade Performance	Company Name	Trade Assignment
10.0	Superintendent	Door Installation
8.0	Superintendent	Framing
10.0	Superintendent	Roofing
7.2	Superintendent	Window Installation

**Project: San Rio**

Trade Performance	Company Name	Trade Assignment
10.0	Superintendent	Electrical
10.0	Superintendent	Exterior Cladding
10.0	Superintendent	Fire Sprinkler
6.3	Superintendent	Framing
10.0	Superintendent	HVAC
10.0	Superintendent	Lath Vendor
10.0	Superintendent	Lathing/Plastering
10.0	Superintendent	Plumbing
10.0	Superintendent	Weather Resistive Barrier

**Quality Built® The Next Generation of Quality Assurance®**

633 S. Andrews Ave. Suite 204, Fort Lauderdale, FL 33301 800.547.5125

Email: [customerservice@qualitybuilt.com](mailto:customerservice@qualitybuilt.com)

10.0	Superintendent	Window Installation
------	----------------	---------------------

**Project: San Rio Ph2 - Site Safety**

Trade Performance	Company Name	Trade Assignment
10.0	Superintendent	Superintendent

**Project: San Rio Ph2(Frankwood Commons)**

Trade Performance	Company Name	Trade Assignment
10.0	Superintendent	Concrete Footings
10.0	Superintendent	Concrete Forming
10.0	Superintendent	Concrete Reinforcement
10.0	Superintendent	Concrete Waterproofing
10.0	Superintendent	Electrical
10.0	Superintendent	Plumbing

**Project: San Rio Unit 3 - GDR has no data at this time**

Trade Performance	Company Name	Trade Assignment
-------------------	--------------	------------------

**Project: Sterling Oaks**

Trade Performance	Company Name	Trade Assignment
10.0	Superintendent	Concrete Footings
10.0	Superintendent	Concrete Forming
10.0	Superintendent	Concrete Reinforcement
10.0	Superintendent	Concrete Waterproofing
10.0	Superintendent	Electrical
10.0	Superintendent	Plumbing

**Project: Summerlin Phase 3 (Andersen Village)**

Trade Performance	Company Name	Trade Assignment
10.0	Superintendent	Concrete Footings
10.0	Superintendent	Concrete Forming
10.0	Superintendent	Concrete Reinforcement
10.0	Superintendent	Electrical

**Quality Built® The Next Generation of Quality Assurance®**

633 S. Andrews Ave. Suite 204, Fort Lauderdale, FL 33301 800.547.5125

Email: [customerservice@qualitybuilt.com](mailto:customerservice@qualitybuilt.com)

10.0	Superintendent	Exterior Cladding
10.0	Superintendent	Fire Sprinkler
10.0	Superintendent	HVAC
1.0	Superintendent	Lath Vendor
10.0	Superintendent	Lathing/Plastering
9.3	Superintendent	Plumbing
10.0	Superintendent	Weather Resistive Barrier
10.0	Superintendent	Wood Framing

**Project: Tiffany Ranch**

Trade Performance	Company Name	Trade Assignment
10.0	Superintendent	Door Installation
10.0	Superintendent	Electrical
10.0	Superintendent	Exterior Cladding
10.0	Superintendent	Fire Sprinkler
10.0	Superintendent	Framing
10.0	Superintendent	HVAC
10.0	Superintendent	Lath Vendor
7.8	Superintendent	Lathing/Plastering
10.0	Superintendent	Plumbing
10.0	Superintendent	Roofing
8.9	Superintendent	Weather Resistive Barrier
10.0	Superintendent	Window Installation
10.0	Superintendent	Wood Framing