



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Bay City Boiler	Type of Inspection:	BC Safety Inspection
Project	kraft boiler 4 tube repair	Date of Inspection	August 22, 2024
Inspector Name	Pete Ellery	Time of Inspection	12:13 PM

NOTES

16 Items Inspected	13 Satisfactory	3 Unsatisfactory	0 N/A
-----------------------	--------------------	---------------------	----------

Ryan
Tony
Joe

INSPECTION ITEMS

General	
Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Unsatisfactory
Comment	
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory
Is drinking water and shade set up sufficient for the amount of workers?	Satisfactory
Is Personal Protective Equipment being worn as required?: Eye, ear, glove, respirator, shoes, and face shield?	Satisfactory
Are scaffolding safety procedures being followed and inspected?: Fully planked, guardrails in place, toe boards, and ladders?	Satisfactory

Are hand and power tools being used safely? Are guards installed on tools?

Unsatisfactory

Comment

Missing guard

Joes grinder



Is good housekeeping being maintained?: Clean work area and sufficient lighting in work area?

Unsatisfactory

Comment

Cords could be laid out better

Created tripping hazard



Is fall protection in place where required? Fall harness and lanyard inspected?

Satisfactory

Are ladders being used safely? Was the ladder inspected and in good condition?

Satisfactory

Are confined space safety procedures being followed?: Permit posted? Was the customer informed of the operation?

Satisfactory

Hot work permit posted? Is the welding screen utilized and fire watch established?

Satisfactory

Are scissor lifts / elevated platforms being used safely?

Satisfactory

Are boom lifts and other aerial devices being used safely?

Satisfactory

Are electrical items being used safely?

Satisfactory

Are all other tasks being performed safely?

Satisfactory

Is lockout/tagout included in the operation? Are proper procedures being followed?

Satisfactory