



**Results for:**  
Safety Orientation

**Company Name:**  
Innovative Metal Industries, Inc.

**Points:**  
100 out of 100

**Duration:**  
2 min, 35 sec

**Percentage:**

**100.00%**

**Employee Name:**  
Steven Gutierrez

**Title:**  
Safety Orientation

**Date finished:**  
Aug Thu August 2023 02:12

**Date started:**  
Aug Thu August 2023 02:09

### Question 1 of 10

**Safety Glasses must be rated Z-87 and Hard hats must be rated Z-89.1.**

Correct answer: **(A)**

Selected answer: **(A)**

A) True

B) False

### Question 2 of 10

**Smoking is allowed anywhere on site.**

Correct answer: **(B)**

Selected answer: **(B)**

A) True

B) False

### Question 3 of 10

**You must be trained and authorized to operate a piece of equipment, including scissor lifts and boom lifts.**

Correct answer: **(A)**

Selected answer: **(A)**

A) True

B) False

### Question 4 of 10

**Forklift operators need to be trained but not certified.**

Correct answer: **(B)**

Selected answer: **(B)**

A) True

B) False

## Question 5 of 10

**A good principle for housekeeping is:**

Correct answer: **(B)**

Selected answer: **(B)**

- A) Only clean up at the end of the day.
- B) Clean as you go.
- C) Clean only if others will be in the area.

## Question 7 of 10

**A hot work permit is needed if you will be performing hot work, such as welding, torching, brazing, or other tasks that create heat or sparks.**

Correct answer: **(A)**

Selected answer: **(A)**

- A) True
- B) False

## Question 9 of 10

**How many points of contact must be kept by a person on a ladder?**

Correct answer: **(B)**

Selected answer: **(B)**

- A) 2
- B) 3
- C) 4

## Question 6 of 10

**Cell phones are allowed to be used while driving equipment.**

Correct answer: **(B)**

Selected answer: **(B)**

- A) True
- B) False

## Question 8 of 10

**There is zero tolerance when it comes to any form of harassment, bullying, or violence in the workplace.**

Correct answer: **(A)**

Selected answer: **(A)**

- A) True
- B) False

## Question 10 of 10

**Extension Cords must be in good working order with no frays or cuts and the ground prong must be in place.**

Correct answer: **(A)**

Selected answer: **(A)**

- A) True
- B) False