



# EQUIPMENT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Cencal Builders	<b>Type of Inspection:</b>	Fork Lift
<b>Project</b>	Brambles (Copper/ willow)- Lennar	<b>Date of Inspection</b>	August 02, 2021
<b>Inspector Name</b>	Robbie Thacker	<b>Time of Inspection</b>	11:05 AM

## INSPECTION ITEMS

Item	Comment	Photo
Click "Satisfactory" and enter the fork lift model # in the comments below	Satisfactory	<p>Genie A TEREX BRAND</p> <p>MODEL: G7700a SERIAL NUMBER: 07080116428 ATTACHMENT: 02 Pro Stack Fork Frame MANUFACTURE DATE: 09/09/21 TOTAL TRUCK WEIGHT: 21420 lbs / 9719 kg MAX LIFT CAPACITY: - 3000 lbs LIFT CAPACITY (LBS) AT MAX LIFT HEIGHT: 6100 lbs OUTRIGGER UP OUTRIGGER DOWN: COUNTRY OF MANUFACTURE: United States MANUFACTURER: Genie Scissor Lifts, Inc. 1200 Quince Orchard Rd. Gaithersburg, MD 20878 United States THIS FORKLIFT TRUCK COMPLIES WITH ANSI 55.6-6</p>
Is the owners manual in place?	Satisfactory	-
Is the seat belt in place and in safe condition?	Satisfactory	-
Is the lift's weight capacity legible?	Satisfactory	-
Is the manufacturer name plate in place and legible?	Satisfactory	-
Do the fork controls operate smoothly and safely?	Satisfactory	-
Do the lift's brakes work?	Satisfactory	-
Does the emergency brake work?	Satisfactory	-
If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturer's instructions?	Satisfactory	-
Is the mast securely in place?	Satisfactory	-
Are the fluid levels good? (oil, fuel, water, etc)	Satisfactory	-
Is the lift free of leaks?	Satisfactory	-
Are hoses and chains in safe condition?	Satisfactory	-
Does the horn work?	Satisfactory	-

Are the headlights and brake lights in good working order?	Satisfactory		-
Is the overhead guard securely in place and in safe condition?	Satisfactory		-
Are the forks in safe condition?	Satisfactory		-
Are the tires in safe condition?	Satisfactory		-
Is the lift in overall good condition?	Satisfactory		