

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

| Company | Cencal Builders | Type of Inspection: | Fork Lift |
|----------------|-----------------------------------|------------------------|-----------------|
| Project | Brambles (Copper/ willow)- Lennar | Date of Inspection | August 10, 2021 |
| Inspector Name | Shawn Garcia | Time of Inspection | 05:59 AM |

INSPECTION ITEMS

| Item | | Comment | Photo |
|--|--------------|---------|--|
| Click "Satisfactory" and enter the fork lift model # in the comments below | Satisfactory | | 1000 0 000 10 00 |
| Is the owners manual in place? | Satisfactory | | - |
| Is the seat belt in place and in safe condition? | Satisfactory | | - |
| Is the lift's weight capacity legible? | Satisfactory | | - |
| Is the manufacturer name plate in place and legible? | Satisfactory | | - |
| Do the fork controls operate smoothly and safely? | Satisfactory | | - |
| Do the lift's brakes work? | Satisfactory | | - |
| Does the emergency brake work? | Satisfactory | | - |
| If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturer's instructions? | Satisfactory | | - |
| Is the mast securely in place? | Satisfactory | | - |
| Are the fluid levels good? (oil, fuel, water, etc) | Satisfactory | | - |
| Is the lift free of leaks? | Satisfactory | | - |
| Are hoses and chains in safe condition? | Satisfactory | | - |
| Does the horn work? | Satisfactory | | - |

| Are the headlights and brake lights in good working order? | Satisfactory | - |
|---|--------------|---|
| Is the overheard guard securely in place and in safe condition? | Satisfactory | - |
| Are the forks in safe condition? | Satisfactory | - |
| Are the tires in safe condition? | Satisfactory | - |
| Is the lift in overall good condition? | Satisfactory | |