




EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Cencal Builders	Type of Inspection:	Fork Lift
Project	Brambles (Copper/ willow)- Lennar	Date of Inspection	August 11, 2021
Inspector Name	Robbie Thacker	Time of Inspection	12:24 PM

INSPECTION ITEMS

Item	Comment	Photo
Click "Satisfactory" and enter the fork lift model # in the comments below	Satisfactory	 <p>Genie A TRACER BRAND</p> <p>MODEL: 1077-504 SERIAL NUMBER: 2142121-1628 ATTACHMENT: EC 214 Fork-Fork Frame MANUFACTURE DATE: 09/07/21 TOTAL TRUCK WEIGHT: 21420 lbs / 9710 kg MAX LIFT CAPACITY: 5,000 lbs LIFT CAPACITY (LBS) AT MAX LIFT HEIGHT: 5,000 lbs OUTDOOR DP OUTDOOR DRAIN COUNTRY OF MANUFACTURE: United States MANUFACTURER: Genie Global Group, Inc. 1000 Corporate Blvd Gardenside, GA 31525 United States THIS FORKLIFT TRUCK COMPLIES WITH ANSI B56.6</p>
Is the owners manual in place?	Satisfactory	-
Is the seat belt in place and in safe condition?	Satisfactory	-
Is the lift's weight capacity legible?	Satisfactory	-
Is the manufacturer name plate in place and legible?	Satisfactory	-
Do the fork controls operate smoothly and safely?	Satisfactory	-
Do the lift's brakes work?	Satisfactory	-
Does the emergency brake work?	Satisfactory	-
If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturer's instructions?	Satisfactory	-
Is the mast securely in place?	Satisfactory	-
Are the fluid levels good? (oil, fuel, water, etc)	Satisfactory	-
Is the lift free of leaks?	Satisfactory	-
Are hoses and chains in safe condition?	Satisfactory	-
Does the horn work?	Satisfactory	-

Are the headlights and brake lights in good working order?	Satisfactory		-
Is the overhead guard securely in place and in safe condition?	Satisfactory		-
Are the forks in safe condition?	Satisfactory		-
Are the tires in safe condition?	Satisfactory		-
Is the lift in overall good condition?	Satisfactory		