




EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Cencal Builders	Type of Inspection:	Fork Lift
Project	Brambles (Copper/ willow)- Lennar	Date of Inspection	September 21, 2021
Inspector Name	Robbie Thacker	Time of Inspection	06:36 AM

INSPECTION ITEMS

Item	Comment	Photo
Click "Satisfactory" and enter the fork lift model # in the comments below	Satisfactory	 <p>Genie MODEL: 371442 SERIAL NUMBER: 07H012-1638 ATTACHMENT: 20' 250' Reach Forklift MANUFACTURE DATE: 8/20/21 TOTAL TRUCK WEIGHT: 21,428 lbs / 9,719 kg MAX LIFT CAPACITY: 6,000 lbs LIFT CAPACITY (LBS) AT MAX LIFT HEIGHT: 6,000 lbs OUTRIGGER UP: OUTRIGGER DOWN: COUNTRY OF MANUFACTURE: USA MANUFACTURER: Terex South Dakota Inc. 600 Seward Road Watertown, SD 57201 United States THIS FORKLIFT TRUCK COMPLIES WITH: ANSI B56.6</p>
Is the owners manual in place?	Satisfactory	-
Is the seat belt in place and in safe condition?	Satisfactory	-
Is the lift's weight capacity legible?	Satisfactory	-
Is the manufacturer name plate in place and legible?	Satisfactory	-
Do the fork controls operate smoothly and safely?	Satisfactory	-
Do the lift's brakes work?	Satisfactory	-
Does the emergency brake work?	Satisfactory	-
If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturer's instructions?	Satisfactory	-
Is the mast securely in place?	Satisfactory	-
Are the fluid levels good? (oil, fuel, water, etc)	Satisfactory	-
Is the lift free of leaks?	Satisfactory	-
Are hoses and chains in safe condition?	Satisfactory	-
Does the horn work?	Satisfactory	-

Are the headlights and brake lights in good working order?	Satisfactory		-
Is the overhead guard securely in place and in safe condition?	Satisfactory		-
Are the forks in safe condition?	Satisfactory		-
Are the tires in safe condition?	Satisfactory		-
Is the lift in overall good condition?	Satisfactory		