




EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Cencal Builders	Type of Inspection:	E12: JLG Forklift G12-55A
Project	Brambles (Copper/ willow)- Lennar	Date of Inspection	May 05, 2022
Inspector Name	Shawn Garcia	Time of Inspection	07:12 AM

INSPECTION ITEMS

Item	Comment	Photo
Click "Satisfactory" and enter the fork lift model # in the comments below	Satisfactory	
Is the owners manual in place?	Satisfactory	-
Is the seat belt in place and in safe condition?	Satisfactory	-
Is the lift's weight capacity legible?	Satisfactory	-
Is the manufacturer name plate in place and legible?	Satisfactory	-
Do the fork controls operate smoothly and safely?	Satisfactory	-
Do the lift's brakes work?	Satisfactory	-
Does the emergency brake work?	Satisfactory	-
If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturer's instructions?	Satisfactory	-
Is the mast securely in place?	Satisfactory	-
Are the fluid levels good? (oil, fuel, water, etc)	Satisfactory	-
Is the lift free of leaks?	Satisfactory	-
Are hoses and chains in safe condition?	Satisfactory	-
Does the horn work?	Satisfactory	-

Are the headlights and brake lights in good working order?	Satisfactory		-
Is the overhead guard securely in place and in safe condition?	Satisfactory		-
Are the forks in safe condition?	Satisfactory		-
Are the tires in safe condition?	Satisfactory		-
Is the lift in overall good condition?	Satisfactory		