

Item

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

| Company | Cencal Builders | Type of Inspection: | E14: Genie GTH-844 Forklift Variable Lift |
|----------------|-----------------------------------|---------------------|---|
| Project | Brambles (Copper/ willow)- Lennar | Date of Inspection | June 07, 2022 |
| Inspector Name | Shawn Garcia | Time of Inspection | 06:12 AM |

INSPECTION ITEMS

Comment

Photo

| item | | Comment | FIIOIO |
|--|--------------|---------|---|
| Click "Satisfactory" and enter the fork lift model # in the comments below | Satisfactory | | MODEL OTHORA SERIAL NUMBERO THORITAGE SERIAL NUMBERO SERIAL NUMBERO SERIAL SERIAL NUMBERO SERIAL NUMBERO SERIAL SERIAL NUMBERO SERIAL NUMBERO SERIAL NUMBERO SERIAL SERIAL NUMBERO |
| Is the owners manual in place? | Satisfactory | | - |
| Is the seat belt in place and in safe condition? | Satisfactory | | - |
| Is the lift's weight capacity legible? | Satisfactory | | - |
| Is the manufacturer name plate in place and legible? | Satisfactory | | - |
| Do the fork controls operate smoothly and safely? | Satisfactory | | - |
| Do the lift's brakes work? | Satisfactory | | - |
| Does the emergency brake work? | Satisfactory | | - |
| If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturer's instructions? | Satisfactory | | - |
| Is the mast securely in place? | Satisfactory | | - |
| Are the fluid levels good? (oil, fuel, water, etc) | Satisfactory | | - |
| Is the lift free of leaks? | Satisfactory | | - |
| Are hoses and chains in safe condition? | Satisfactory | | - |
| Does the horn work? | Satisfactory | | - |

| Are the headlights and brake lights in good working order? | Satisfactory | - |
|---|--------------|---|
| Is the overheard guard securely in place and in safe condition? | Satisfactory | - |
| Are the forks in safe condition? | Satisfactory | - |
| Are the tires in safe condition? | Satisfactory | - |
| Is the lift in overall good condition? | Satisfactory | |