



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

| | | | |
|-----------------------|--------------------------------|----------------------------|---------------|
| Company | Cencal Builders | Type of Inspection: | Boom Lift |
| Project | Copper River Apt | Date of Inspection | July 13, 2021 |
| Inspector Name | jesus.cencalbuilders@gmail.com | Time of Inspection | 09:28 AM |

INSPECTION ITEMS

| Item | Comment | Photo |
|---|--------------|-------|
| Click "Satisfactory" and enter the boom lift model # in the comments below | Satisfactory | - |
| Is the lift in overall good condition and the platform clean? | Satisfactory | - |
| Are there full body harnesses available with the correct lanyard for those working in the basket? | Satisfactory | - |
| Are the indicator lights working? | Satisfactory | - |
| Perform a platform control check. Does everything operate smoothly? | Satisfactory | - |
| Perform a ground control check. Does everything operate smoothly? | Satisfactory | - |
| Are the tires in safe condition? | Satisfactory | - |
| Are the platform anchor point(s) in place and clearly labeled? | Satisfactory | - |
| Are the guardrails and platform door in securely in place? | Satisfactory | - |
| Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals? | Satisfactory | - |
| Is the owners manual in place? | Satisfactory | - |
| Are the structure, pins and covers in good condition? | Satisfactory | - |
| Does the horn work? | Satisfactory | - |
| Is the moving alarm working? | Satisfactory | - |